



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/JOANNE TAN JONG HENG
	Reg No/Reg Date	SMF2257C / 31/10/201
	Date In/Mileage	19/11/2021/ 0
	Chassis No	KNAF3416MK5019831
	Engine No	G4FGJH709009
	Make/Model	KIA/CERATO 1.6 A SR SX G335
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	22/11/2021/ 18:03	BLK	282 / Kevin Leong	42813
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	REPLACE REAR BUMPER, END PANEL, BOOT & AFFECTED AREA 4.5 X 400				1800 2400.00
	REPAIR ON FLOOR PANEL & REAR LH FENDER 1/2				
E PNT98000	PAINT WORK ON REAR BUMPER, BOOT, END PANEL, REAR LH FENDER & FLOOR PANEL 4 X 350				1400 1750.00
E PNT88000	REMOVE & REPLACE REAR PARKING ASSIST				80 120.00
E PNT88000	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR				120.00
E PNT88000	TO TANSFER REAR BOOT ATTACHMENTS TO NEW PANEL				120.00
M SUNDRY	TO APPLY SEALANT ON AFFECTED AREA				80.00
M SUNDRY	PERFORM RUST PREVENTION				40 80.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY	TO SUPPLY C & C EMBLEM				40.00
M SUNDRY	TO SUPPLY REAR NUMBER PLATE WITH FRAME				X 50.00
A 15900099	REPLACE REAR EXHAUST MUFFLER				3X 400.00
M SUNDRY	SUNDRIES				20 50.00
M LAMP ASSY-REAR COMB INSIDE,LH	1.00	608.00	20.00		486.40
M LAMP ASSY-REAR COMB INSIDE,RH	1.00	608.00	20.00		486.40
M LAMP ASSY-REAR COMB OUTSIDE,LH	1.00	675.00	20.00		540.00
M LAMP ASSY-REAR COMB OUTSIDE,RH	1.00	675.00	20.00		540.00
M LAMP ASSY-CENTER GARNISH	1.00	690.00	20.00		552.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /JOANNE TAN JONG HENG Reg No/Reg Date SMF2257C / 31/10/201 Date In/Mileage 19/11/2021/ 0 Chassis No KNAF3416MK5019831 Engine No G4FGJH709009 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
LAX00000	Credit	22/11/2021/ 18:03	BLK	282 / Kevin Leong	42813	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
M	MUFFLER ASSY-REAR	1.00	757.00	20.00	605.60	
M	GASKET-EXHAUST PIPE	1.00	14.00	20.00	11.20	
M	PANEL ASSY-TRUNK LID	1.00	1297.00	20.00	1037.60	
M	PANEL ASSY-BACK	1.00	324.00	20.00	259.20	
M	EMBLEM-CERATO	1.00	28.00	20.00	22.40	
M	LOGO ASSY-KIA SUB	1.00	32.00	20.00	25.60	
M	COVER-RR BUMPER	1.00	651.00	20.00	520.80	
M	COVER-RR BUMPER LWR	1.00	241.00	20.00	192.80	
M	COVER-RR BUMPER UNDER, LH	1.00	33.00	20.00	26.40	
M	COVER-RR BUMPER FOG LAMP, LH	1.00	88.00	20.00	70.40	
M	COVER-RR BUMPER FOG LAMP, RH	1.00	88.00	20.00	70.40	
M	LAMP ASSY-SIDE T/SIGNAL, LH	1.00	181.00	20.00	144.80	
M	LAMP ASSY-SIDE T/SIGNAL, RH	1.00	181.00	20.00	144.80	
M	EXTN WIRING ASSY-BWS	1.00	207.00	20.00	165.60	
M	BRACKET-RR BEAM UPR MTG, LH	1.00	9.00	20.00	7.20	
M	BRACKET-RR BEAM UPR MTG, RH	1.00	9.00	20.00	7.20	
M	BRACKET-RR BEAM LWR, CTR	1.00	6.00	20.00	4.80	
M	BRACKET-RR BEAM LWR MTG	1.20	6.00	20.00	9.60	
M	BEAM-RR BUMPER	1.00	318.00	20.00	254.40	
M	ANTENNA ASSY-SMARTKEY	1.00	46.00	20.00	36.80	
M	STAY-RR BUMPER LH	1.00	65.00	20.00	52.00	
M	STAY-RR BUMPER RH	1.00	65.00	20.00	52.00	
M	BRACKET ASSY-RR BPR SIDE UPR, L	1.00	25.00	20.00	20.00	
M	BRACKET ASSY-RR BPR SIDE UPR, R	1.00	31.00	20.00	24.80	
M	ULTRASONIC SENSOR ASSY-BWS	1.00	163.00	20.00	130.40	
M	ULTRASONIC SENSOR ASSY-BWS	1.00	163.00	20.00	130.40	
M	ULTRASONIC SENSOR ASSY-BWS	1.00	163.00	20.00	130.40	

Estimate

Steve (LKK)
23/11/21, 10:00am

00-NM HL
E-xcess-?
P/P

LKK Auto Consultants hence notify

Steve (LKK)
23/11/21, 10:00am

00-NM HL
EXCISE-?
P/P

My BCL Ry

13 & days

Confirm & accepted by

LKK Auto Consultant's hence notify
the Repairer of the following.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

Nett 12,122.40
7% GST on 12122.40 848.57
Total Payable 12,970.97

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.