

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte.	Cust No/Name	/JOANNE TAN JONG HENG	
Ltd.	Reg No/Reg Date		
MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16	Date In/Mileage	112	
AIG BUILDING	Chassis No	KNAF3416MK5019831	
SINGAPORE 079120	Engine No	G4FGJH709009	
Contact No 64191000	The state of the s	KIA/CERATO 1.6 A SR SX G335	
		B4U GRAVITY BLUE / WK SATURN BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	
LAX00000	Credit	22/11/2021/ 18:03	BLK	282 / Kevin Leong]	42813	
E PNT88000		Description of Goods	s / Service	es	Qty	Unit Price Dis	c% Amount
REPLACE REPAIR O	REAR BUMP N FLOOR P	PER, END PANEL, BOOT PANEL & REAR LH FENDE	& AFFECT	ED AREA			2400.00
PAINT WO FLOOR PA	RK ON REA	R BUMPER, BOOT, END		EAR LH FENDER &			1750.00
E PNT88000 REMOVE & E PNT88000	REPLACE	REAR PARKING ASSIST					120.00
REMOVE &	INSTALL	REAR BOOT COMPARTMEN	T FOR FA	CILITATE REPAIR			120.00
TO TANSFI M SUNDRY	ER REAR B	OOT ATTACHMENTS TO N	EW PANEL		46	\	120.00
TO APPLY M SUNDRY	SEALANT	ON AFECTED AREA	5) [[[E	7	80.00
PERFORM F A 54900099							80.00
	RING & CH	ASSIS ELECTRICAL SYS	TEM				30.00
	OUT DIAG	NOSTIC CHECK ON ELEC	TRONIC CO	ONTROL SYSTEM			120.00
TO SUPPLY SUNDRY	C & C EN	MBLEM					40.00
	REAR NUM	MBER PLATE WITH FRAME	Ē				50.00
	EAR EXHAU	JST MUFFLER					400.00
SUNDRIES	_DEAD COM	MB INSIDE,LH					50.00
I LAMP ASSY I LAMP ASSY	-REAR COM -REAR COM -REAR COM	B INSIDE,RH B OUTSIDE,LH B OUTSIDE.RH			1.00 1.00 1.00 1.00	608.00 20.0 608.00 20.0 675.00 20.0 675.00 20.0 690.00 20.0	0 486.40 0 540.00 0 540.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte.	Cust No/Name	/JOANNE TAN JONG HENG	
Ltd.	Reg No/Reg Date		
MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16	Date In/Mileage		
AIG BUILDING	Chassis No	KNAF3416MK5019831	
SINGAPORE 079120	Engine No	G4FGJH709009	
Contact No 64191000	Make/Model	KIA/CERATO 1.6 A SR SX G335	
		B4U GRAVITY BLUE / WK SATURN BLACK	

Account No	Terms	Date/Time Pri		CSE	Operator		WIP No		
AX00000	Credit	22/11/2021/		BLK	282 / Kevin Leong		42813		
MUEEL EE	1004 ==	Description of	of Goods	/ Services		Qty	Unit Price	Disc%	Amount
MUFFLER A						1.00	757.00		605.6
						1.00		20.00	11.2
PANEL AS:		LID				1.00	1297.00		1037.6
M EMBLEM-CI						1.00	324.00		259.2
LOGO ASS						1.00		20.00	22.4
COVER-RR)				1.00		20.00	25.6
COVER-RR		MD				1.00	651.00		520.8
COVER-RR						1.00	241.00		192.8
COVER-RR	RIIMDED E	OG LAMP,LH				1.00	33.00	20.00	26.4
COVER-RR	RIIMPED E					1.00		20.00	70.4
LAMP ASSY	-SIDE T/	SIGNAL, LH		$\neg $ \bot \Box	mai	1.00		20.00	70.4
LAMP ASSY	-SIDE T/	SIGNAL, RH	\neg (27711	10000	1.00	181.00		144.8
EXTN WIRI	NG ASSY-	RWS L	- 17	201111		1.00	181.00		144.8
		PR MTG,LH			11 11 CT	4.60	207.00		165.6
BRACKET-R	R BEAM III	PR MTG,RH				1.00		20.00	7.2
BRACKET-R	R BEAM II	WR CTR				1.00		20.00	7.2
BRACKET-R	R BEAM LI	WR MTG				1.00		20.00	4.8
BEAM-RR B						2.00		20.00	9.6
ANTENNA A		TKEY				1.00	318.00	(1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.	254.4
STAY-RR B						1.00	46.00		36.8
STAY-RR B	UMPER RH					1.00	65.00	A CONTRACTOR OF THE PARTY OF TH	52.0
BRACKET A	SSY-RR BE	PR SIDE UPR,L				1.00	65.00		52.0
BRACKET-A	SSY RR BE	PR SIDE UPR.R				1.00	25.00		20.0
ULTRASONI	C SENSOR	ASSY-BWS				1.00	31.00		24.8
ULTRASONI	C SENSOR	ASSY-BWS				1.00 1.00	163.00		130.40
ULTRASONI	C SENSOR	ASSY-BWS				1.00	163.00 163.00		130.40
						1100	103.00	20.00	130.40
onfirm & ac	cepted by						Net		12,122.4
					7%	GST on	12122.40)	848.5
unth and						Tota	l Payable	•	12,970.9
utnorized s	ignatory a	and company sta	amp						

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.