

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/GRB21011877/AVF3E2

Date: 12/01/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SMR199L **Insured Vehicle No :** SLR4118G
Date of Loss: 20/11/2021 Nature of Claim: TP Claim No: MFL2021D0005037

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR199L**
Make & Model: HONDA HR-V, 1.5 DX CVT (A) Engine No: L15B5672239
Reg. Date: 06/12/2019 (Man. Year: 2019) Chassis No: JHMRU1810JX202235
Colour: Black Odometer: 108184 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,406.10	2,082.32	2,323.78	52.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	1,620.00	1,610.00	49.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,636.10	3,702.32	3,933.78	51.52
Approved Total (Overridden) (S\$)		2,900.00		
Nett Amount (S\$)	7,636.10	2,900.00	4,736.10	62.02

INSPECTION

Date of Assignment: 23/11/2021
Date Inspected: 24/11/2021 Inspected At: Automobile Hub Enterprise
Estimated Period of Repair: 4.0 days 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT Singapore 417883

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Jan 2022)	
Parts:	N/A	HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR199L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	467.90 F	*467.90 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	2		*REAR BUMPER SIDE HOLDER	Necessary	48.20 F	*48.20 FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	339.20 F	*- FL
5	1		*REAR END PANEL	Repair	378.40 F	*- FL
6	1		*REAR END PANEL TOP GARNISH	Not Necessary	44.90 F	*- FL
7	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
8	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
9	2		*TAILLAMP LOWER APRON	Deformed	390.00 F	*390.00 FL
10	1		*TAILGATE	Dented	867.00 F	*867.00 FL
11	1		*TAILGATE LOCK	Damaged	165.30 F	*165.30 FL
12	1		*TAILGATE WEATHERSTRIPE	Not Necessary	102.40 F	*- FL
13	1		*TAILGATE INNER TRIM BOARD	Cracked	189.40 F	*189.40 FL
14	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
15	1		*TAILGATE GLASS MOULDING	Necessary	75.10 F	*75.10 FL
16	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
17	1		*REAR EXHAUST PIPE	Not Necessary	520.80 F	*- FL
18	1		*REAR EXHAUST MOUNTING	Not Necessary	58.00 F	*- FL
19	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	299.50 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,406.10	2,522.90
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	440.58
Total Parts (\$\$)	4,406.10	2,082.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	600.00
2	SPRAY PAINTING	New	1,000.00	600.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO SPRAY TUFF COAT	New	150.00	50.00
7	TO REMOVE UPHOLSTERY	New	150.00	40.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO REMOVE EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (\$\$)			3,230.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >