

SMR 199L 2019 Dec

TP111

Honda HRV 1496 cc

Veron.

JHMRU1810JX202235

Rear Bumper	Deformed	467.90 /
Rear Bumper Clips.	Ner	30(SN) /
Rear Bumper Side Holder x02	Ner	$24.1 \times 2 = 48.20$ /
Rear Bumper Reflector x02	Ner	$169.6 \times 2 = 339.20$ X
Rear End Panel	Repis	378.40 +
Rear End Panel Top Garnish.	Ner	44.50 X
Rear End Panel Sealant.	Ner	60(SN) +
Reverse Sensor	Damaged	280(SN) 200(SN)
Taillamp Lower Apron x02	Deformed	$195 \times 2 = 390$ /
Tailgate	Dented	867 /
Tailgate Lock	Damaged	165.30 /
Tailgate Weatherstripe	Ner	102.40 X.
Tailgate Inner Trim Board	Cracked	189.40 /
Tailgate Inner Trim Board Clips.	Ner	30(SN) /

3392.70

SMR 199L.

Tailgate G/s) Moulding.	2	75.10	-
Tailgate G/s) Sealant.	1	60(su)	-
Rear Exhaust Pipe.	2	520.80	x
Rear Exhaust Mounting.	1	58	x
Spare Tyre Panel Top Cover.	1	299.50	x
	220250	S.N: 320	
	176232		
Panel Beating		1200	600
Spray Painting.		1000	600
Wiring.		50	30
To remove reverse sensor		100	50
To remove rear camera		100	50
To spray tuff coat		150	50
To remove upholstery.		150	40
To transfer tailgate fittings.		150	80
To remove tailgate g/s)		180	120

SMR199L

To remove exhaust pipe . 150 X
1620

7636.10

total: 3702.32

L/s: 2.9K.

04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

