

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21011878/BNF3E2

Date: 23/08/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001931482
Claimant Vehicle No :	SKH8852H	Insured Vehicle No :	SLP667A
Date of Loss:	20/11/2021	Nature of Claim:	TP
		Claim No:	265771

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH8852H		
Make & Model:	MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A)	Engine No:	4A92AY0050
Reg. Date:	25/01/2013 (Man. Year: 2012)	Chassis No:	JMYSRCY1ACU000664
Colour:	Black	Odometer:	165214 km
Engine Capacity:	1590 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,901.38	2,157.06	5,744.32	72.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,000.00	1,700.00	62.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,601.38	3,157.06	7,444.32	70.22
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	10,601.38	2,300.00	8,301.38	78.30
+ GST 7.00/7.00% (S\$)	742.10	161.00	581.10	78.30
Nett Amount (S\$)	11,343.48	2,461.00	8,882.48	78.30

INSPECTION

Date of Assignment:	24/11/2021	
Date Inspected:	22/11/2021 Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: Lim Teow Guan

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Dec 2021)

Parts: 143 MITSUBISHI LANCER 1.6 EX AT LED TAIL LAMP (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKH8852H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Damaged	1,326.30 FL	*- FL
2	1		*FRONT BUMPER	Cut	955.40 FL	*858.00 FL
3	1		*FRONT BUMPER RETAINER LH	Necessary	62.20 FL	*25.40 FL
4	1		*FRONT BUMPER MITSUBISHI LOGO	Necessary	82.80 FL	*43.00 FL
5	1		*FRONT FOGLAMP COVER LH	Dislodged	58.00 FL	*58.00 FL
6	1		*FRONT FOGLAMP LH	Not Damaged	102.00 FL	*- FL
7	1		*HEADLAMP LH	Cut	791.00 FL	*791.00 FL
8	1		*HEADLAMP LOWER BRACKET LH	No such part	77.80 FL	*- FL
9	1		*FRONT FENDER LH	Dented	908.00 FL	*588.00 FL
10	1		*FRONT FENDER INNER SHIELD LH	Not Damaged	201.90 FL	*- FL
11	1		*FRONT LOWER ARM LH	Not Damaged	303.10 FL	*- FL
12	1		*FRONT KNUCKLE ARM LH	Not Damaged	503.80 FL	*- FL
13	1		*FRONT ABSORBER LH	Not Damaged	515.20 FL	*- FL
14	1		*FRONT STABILIZER LINK LH	Not Damaged	123.90 FL	*- FL
15	1		*FRONT TIE ROD LH	Not Damaged	98.10 FL	*- FL
16	1		*FRONT WHEEL BEARING LH	Not Damaged	118.70 FL	*- FL
17	1		*FRONT DRIVESHAFT LH	Not Damaged	1,390.00 FL	*- FL
18	1		*FRONT SPORT RIM	Not Damaged	850.00 FS	*- FS
19	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
20	1		*FRONT FENDER SPLASH SHIELD CLIP	Not Necessary	50.00 FS	*- FS
21	1		*LH FRONT TYRE	Not Damaged	95.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,663.20	2,393.40
- List Item Discount on L Items 10.00/10.00% (\$)	761.82	236.34
Total Parts (\$)	7,901.38	2,157.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	New	1,000.00	600.00
2	BEFORE AND AFTER WHEEL ALIGNMENT	New	100.00	0.00
3	LABOUR FOR UNDERCARRIAGE	New	250.00	0.00
4	TO RESPRAY UNDERCOATING ON PARTS REPLACED	New	200.00	0.00
5	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	New	1,000.00	400.00
6	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (\$\$)			2,700.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >