

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21011882/AEA3Q2**Date:** 29/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210031872
<b>Claimant Vehicle No :</b>	SLF6451T	<b>Insured Vehicle No :</b>	SMY9439Z
Date of Loss:	18/11/2021	Nature of Claim:	TP
		Claim No:	6005924965SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLF6451T</b>		
Make & Model:	HYUNDAI ACCENT (RB), 1.4 5DR CVT ABS D/AB 2WD (A)	Engine No:	G4LCGU626390
Reg. Date:	02/09/2016 (Man. Year: 2016)	Chassis No:	KMHCT51BTGU294762
Colour:	Black	Odometer:	73007 km
Engine Capacity:	1368 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,303.40	1,757.20	546.20	23.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,510.00	540.00	26.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,353.40</b>	<b>3,267.20</b>	<b>1,086.20</b>	<b>24.95</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,353.40</b>	<b>2,600.00</b>	<b>1,753.40</b>	<b>40.28</b>
<b>+ Car Rental (4.0 x S\$90.00/day) (S\$)</b>		360.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>+ Other Costs (S\$)</b>		80.00		
<b>Nett Liability (S\$)</b>		<b>3,047.45</b>		

INSPECTION

Date of Assignment:	19/11/2021	
Date Inspected:	19/11/2021	Inspected At: Ysk Auto Workshop (HQ) No.1 Kaki Bukit Avenue 6, #01-49 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	443.90 F	*443.90 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*REAR BUMPER SIDE HOLDER RH	Damaged	31.20 F	*31.20 FL
4	1		*REAR BUMPER REFLECTOR RH	Cracked	64.00 F	*64.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Cracked	376.00 F	*376.00 FL
6	1		*REAR BUMPER REINFORCEMENT STAY RH	Not Necessary	84.40 F	*- FL
7	1		*REAR BUMPER MUDFLAP RH	Cut	85.10 F	*85.10 FL
8	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
9	1		*REAR END PANEL	Dented	499.30 F	*499.30 FL
10	1		*TAILLAMP RH	Cracked	326.50 F	*326.50 FL
11	1		*HYUNDAI LOGO	Necessary	45.00 F	*45.00 FL
12	1		*ACCENT EMBLEM	Necessary	38.00 F	*38.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,303.40	2,139.00
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	381.80
Total Parts (S\$)	2,303.40	1,757.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	800.00	650.00
2	SPRAY PAINTING	New	800.00	700.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	40.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	150.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,050.00</b>	<b>1,510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >