

TPA 16.
Ashes.

SLF6451T. 2016 Sept.
Hyundai Accent. 1368cc
KMHCT51BT64294762

Rear Bumper	Distorted	443.90 /
		30(SN) /
Rear Bumper Clips.	NC	31.20 /
Rear Bumper Side Holder RH.	Dmg	64 /
Rear Bumper Reflector RH.	Crushed	376. /
Rear Bumper Reinforcement.	Crushed	84.40 +
	rem	
Rear Bumper Reinforcement Stay RH.		85.10 /
Rear Bumper Mud Flap RH.	cut	280(SN) 200(SN)
Reverse Sensor	Damaged	499.30 ✓
Rear End Panel.	Dented.	326.50 ✓
Taillamp RH.	Crushed	45 /
Hyundai Logo.	} NC	38 /
Accent Emblem		

119090

15277205 N:230

SLF 6451 T.

Panel Beating

~~800~~ 650

Spray Painting.

~~800~~ 700

Wiring.

~~50~~ 30

To spray tuft coat.

~~150~~ 40

To remove reuse sensor

~~100~~ 50

To remove upholstery.

150 ~~150~~ 40

Total: 3267.20

1/s: 2.6k

04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: