



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 5127A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT MIRROR COMPLETE SET LH	CRACKED	1,159.70	1,159.70
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,620.00	-
	LESS 25% DISCOUNT		-694.93	-289.93
			2,084.77	869.77
	<u>LABOUR</u>			
	ANTI-RUST COATING.	NOT NECESSARY	80.00	-
	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS,PANEL BEAT,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR LH.		600.00	120.00
	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.		600.00	280.00
	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING.		150.00	20.00
	DISMANTLE AND TRANSFER DOOR AND MECHANISM TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-
			1,550.00	420.00
	GRAND TOTAL		3,634.77	1,289.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,000.00

Report Ref No. CS/AGI21011883/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.