

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAL	_ INSURANCE (S) PL	Re	ef: CS/AGI21011885/Aqf3n2		
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate: 20/12/2021		
			Co	ode: AGI		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SME 4812S	Veh. Inspected	PC 7556L		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	C10012577/JM	Excess (\$)	0.00		
	Assign From	IVY RATILLA	Assign Date	23/11/2021		
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE	c.c	2982		
	Engine No.	HIDDEN	Year of Reg.	2018		
	Chassis No.	JTFST22P400038070	Colour	WHITE		
	Odometer	203148 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	NIL		
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make	Balance		
	R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm		
	L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm		
	R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm		
	L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm		
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	20/11/2021	Inspection Date	24/11/2021		
	Survey held at 2020 SPRAY PAINTING PTE LTD					
		53 UBI AVENUE 1, #05-15, PAYA UBI INDUSTRIAL PARK, SINGAPORE 408934				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate I	Days of Repair			

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: