

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011892/BPA3Q2**Date:** 06/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210103034
Claimant Vehicle No :	SKS3957P	Insured Vehicle No :	GBH1157J
Date of Loss:	22/11/2021	Nature of Claim:	TP
		Claim No:	5564705069SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS3957P	Engine No:	2AZ1A86987
Make & Model:	TOYOTA PREVIA, 2.4 7-seater (A)	Chassis No:	JTEGD56MX07166152
Reg. Date:	15/10/2018 (Man. Year: 2018)	Odometer:	65841 km
Colour:	Blue		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,019.92	9,626.38	15,393.54	61.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,050.00	2,890.00	4,160.00	59.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	32,069.92	12,516.38	19,553.54	60.97
Approved Total (Overridden) (\$\$)		10,000.00		
(\$\$)	32,069.92	10,000.00	22,069.92	68.82
+ GST 7.00/7.00% (\$\$)	2,244.89	700.00	1,544.89	68.82
Nett Amount (\$\$)	34,314.81	10,700.00	23,614.81	68.82
+ Car Rental (16.0 x \$S\$130.00/day + 7.00% GST) (\$\$)		2,225.60		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		12,933.05		
Global Sum Settlement (\$\$)		12,900.00		

INSPECTION

Date of Assignment:	22/11/2021	
Date Inspected:	22/11/2021	Inspected At: 160 SIN MING DRIVE #01-14
Estimated Period of Repair:	14.0 days	Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,145.00 FL	*1,324.00 FL
2	1		*TAILGATE LOGO	Necessary	68.00 FL	*68.00 FL
3	1		*TAILGATE EMBLEM TOYOTA	Necessary	60.00 FL	*49.70 FL
4	1		*TAILGATE EMBLEM PREVIA	Necessary	68.00 FL	*51.60 FL
5	1		*TAILGATE OUTER CHROME GARNISH	Broken	294.80 FL	*240.90 FL
6	1		*TAILGATE INNER TRIM BOARD	Broken	584.10 FL	*384.10 FL
7	2		*TAILGATE INNER TRIM BOARD SIDE	Not Damaged	364.00 FL	*- FL
8	1		*TAILGATE INNER TRIM BOARD UPPER	Not Damaged	195.00 FL	*- FL
9	1		*TAILGATE INNER HANDLE	Not Necessary	84.00 FL	*- FL
10	2		*TAILGATE LAMP	Broken	1,163.20 FL	*676.80 FL
11	1		*TAILGATE LAMP CENTER LAMP	Broken	477.00 FL	*179.34 FL
12	1		*TAILGATE WEATHERSTRIP	Torn	498.45 FL	*398.50 FL
13	1		*TAILGATE INNER LOCK	Jammed	381.40 FL	*381.40 FL
14	1		*TAILGATE INNER LOCK MOTOR	Scratched	589.45 FL	*589.45 FL
15	1		*TAILGATE INNER LOCK CATCH	Not Damaged	32.10 FL	*- FL
16	1		*TAILGATE LOCK STRIKER	Not Damaged	58.00 FL	*- FL
17	1		*TAILGATE SOLENOID SWTICH	Not Damaged	475.80 FL	*- FL
18	2		*TAILGATE LOCK SENSOR	Not Damaged	372.00 FL	*- FL
19	1		*TAILGATE WINDSCREEN MOULDING	Necessary	287.20 FL	*160.00 FL
20	1		*TAILGATE WIPER ARM	Not Damaged	141.00 FL	*- FL
21	1		*TAILGATE WIPER MOTOR	Not Damaged	891.60 FL	*- FL
22	2		*TAILGATE HINGE	Not Damaged	190.00 FL	*- FL
23	2		*TAILGATE NUMBER PLATE LAMP	Not Damaged	167.10 FL	*- FL
24	1		*REAR BUMPER	Broken	1,287.10 FL	*847.80 FL
25	2		*REAR BUMPER SIDE RETAINER	Necessary	288.00 FL	*96.40 FL
26	2		*REAR BUMPER SIDE RETAINER SIDE	Necessary	264.00 FL	*264.00 FL
27	1		*REAR BUMPER REFLECTOR	N/S Broken	195.00 FL	*97.50 FL
28	2		*REAR BUMPER LOWER BRACKET	No such part	342.90 FL	*- FL
29	1		*REAR BUMPER TOW COVER	N/S Missing	122.20 FL	*48.50 FL
30	1		*REAR BUMPER INNER SPONGE	Broken	186.00 FL	*186.00 FL
31	1		*REAR END PANEL INNER	Dented	984.70 FL	*688.60 FL
32	1		*REAR END PANEL OUTER	Damaged	891.40 FL	*648.10 FL
33	1		*REAR END PANEL TOP GARNISH	Broken	389.00 FL	*277.85 FL
34	1		*REAR END PANEL INNER GARNISH	Broken	361.60 FL	*280.00 FL
35	1		*REAR WELL PANEL	Dented	988.85 FL	*680.00 FL
36	1		*REAR WELL PANEL TRIM	No such part	561.45 FL	*- FL
37	1		*REAR WELL PANEL TOP COVER	Not Damaged	242.10 FL	*- FL
38	1		*REAR FENDER	Repair	2,946.00 FL	*- FL
39	1		*REAR FENDER INNER PANEL	N/S Dented	1,620.60 FL	*810.30 FL
40	2		*REAR FENDER INNER TRIM BOARD	Broken	1,400.00 FL	*1,400.00 FL
41	2		*REAR FENDER INNER COWLING	Not Necessary	236.00 FL	*- FL
42	2		*REAR FENDER SIDE GLASS MOULDING	Not Necessary	251.60 FL	*- FL
43	1		*REAR FENDER AIR VENTS	No such part	167.00 FL	*- FL
44	2		*TAIL LAMP	Broken	969.00 FL	*969.00 FL
45	2		*TAIL LAMP LOWER BRACKET	No such part	168.00 FL	*- FL
46	2		*TAIL LAMP BASE PANEL	Not Necessary	999.60 FL	*- FL
47	1		*EXHAUST PIPE	No such part	682.50 FL	*- FL
48	2		*EXHAUST PIPE MOUNTING	No such part	85.00 FL	*- FL
49	1		*REAR A/C COOLING COIL	No such part	1,405.30 FL	*- FL
50	1		*REAR A/C BLOWER MOTOR	No such part	298.60 FL	*- FL
51	1		*REAR A/C COOLING RUBBER PIPING	No such part	849.60 FL	*- FL
52	1		*REAR TOOL BRACKET	Bent	264.00 FL	*264.00 FL
53	1		*REAR TOOL TRAYS COVER	No such part	445.60 FL	*- FL
54	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
55	1		*TAILGATE SEALANT	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*TAILGATE OUTER CHROME GARNISH CLIPS	Necessary	50.00 FS	*10.00 FS
57	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
58	2		*TAILGATE LAMP SEAL	Necessary	120.00 FS	*60.00 FS
59	2		*TAILGATE LAMP CLIPS	Not Necessary	100.00 FS	*- FS
60	1		*TAILGATE CENTER LAMP SEAL	No such part	60.00 FS	*- FS
61	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
62	1		*TAILGATE WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
63	1		*TAILGATE WINDSCREEN CLIPS	Not Necessary	50.00 FS	*- FS
64	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Not Necessary	100.00 FS	*- FS
65	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
66	4		*REAR BUMPER REVERSE SENSOR	Scratched	740.00 FS	*200.00 FS
67	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
68	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
69	1		*REAR WELL PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
70	2		*TAIL LAMP SEAL	Necessary	120.00 FS	*40.00 FS
71	2		*TAIL LAMP CLIPS	Not Necessary	100.00 FS	*- FS
72	1		*TAIL LAMP BASE PANEL SEALANT	N/S Necessary	200.00 FS	*30.00 FS
73	1		*REAR NUMBER PLATE W/CASING	Necessary	80.00 FS	*30.00 FS
74	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	32,389.90	12,641.84
- List Item Discount on L Items 25.00/25.00% (\$\$)	7,369.98	3,015.46
Total Parts (\$\$)	25,019.92	9,626.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	300.00	120.00
3	R&R REVERSE SENSOR	New	120.00	60.00
4	R&R REAR FENDER SIDE GLASS	New	500.00	0.00
5	R&R FUEL TANK PIPE	New	150.00	0.00
6	R&R EXHAUST PIPE	New	150.00	0.00
7	R&R REAR SEAT	New	400.00	80.00
8	R&R REAR A/C COLING COIL	New	150.00	0.00
9	CHECK WIRING	New	80.00	30.00
10	MOUNT WORK BENCH	New	350.00	0.00
11	CHASSIS ALIGNMENT	New	300.00	0.00
12	UPHOLSTERY	New	300.00	0.00
13	DIAGNOSTIC & RESET FAULT CODE	New	300.00	120.00
14	PANEL BEATING	New	1,800.00	1,400.00
15	RUST PROOFING	New	200.00	0.00
16	SPRAY PAINTING	New	1,800.00	1,000.00
Gross Labour Cost (S\$)			7,050.00	2,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >