

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21011893/AEA3Q2**Date:** 05/05/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0005826_01

Claimant Vehicle No : SMG6862Z **Insured Vehicle No :** SMV6131X

Date of Loss: 20/11/2021 Nature of Claim: TP Claim No: MFL2021D0005072

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG6862Z**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 Elegance (A) Engine No: 1ZR0C77422

Reg. Date: 28/12/2018 (Man. Year: 2018) Chassis No: MR053REH604594302

Colour: Silver Odometer: 58975 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,021.50	8,050.50	10,971.00	57.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	3,240.00	1,660.00	33.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,921.50	11,290.50	12,631.00	52.80
Approved Total (Overridden) (\$\$)		9,000.00		
(\$\$)	23,921.50	9,000.00	14,921.50	62.38
+ GST 7.00/7.00% (\$\$)	1,674.51	630.00	1,044.51	62.38
Nett Amount (\$\$)	25,596.01	9,630.00	15,966.01	62.38
+ Car Rental (13.5 x S\$100.00/day) (\$\$)		1,350.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		10,987.45		
Global Sum Settlement (\$\$)		10,950.00		

INSPECTION

Date of Assignment: 23/11/2021

Date Inspected: 23/11/2021 Inspected At:

Progressive Car Care Pte Ltd (HQ)
Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716

Estimated Period of Repair: 11.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Feb 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 Elegance (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMG6862Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	486.00 FL	*486.00 FL
2	2		*REAR BUMPER SIDE HOLDER -LH/RH	Necessary	220.00 FL	*220.00 FL
3	2		*REAR BUMPER SIDE BRACKET -LH/RH	Not Necessary	126.00 FL	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Dented	395.00 FL	*395.00 FL
6	2		*REAR BUMPER REFLECTOR -LH/RH	Not Necessary	126.00 FL	*- FL
7	1		*REAR BOOT	Dented	755.00 FL	*755.00 FL
8	1		*REAR BOOT INSULATOR	Not Necessary	455.00 FL	*- FL
9	1		*REAR BOOT TOP LOCK	Damaged	382.00 FL	*382.00 FL
10	1		*REAR BOOT BOTTOM LOCK	Not Necessary	30.00 FL	*- FL
11	1		*REAR BOOT TOYOTA EMBLEM	Necessary	78.00 FL	*78.00 FL
12	1		*REAR BOOT COROLLA ALTIS WORDING	Necessary	70.00 FL	*70.00 FL
13	2		*REAR BOOT HINGE-LH/RH	Not Necessary	140.00 FL	*- FL
14	1		*REAR BOOT CHROME MOULDING	Not Necessary	435.00 FL	*- FL
15	2		*REAR BOOT LAMP -LH/RH	Not Necessary	802.00 FL	*- FL
16	1		*REAR BOOT RUBBER	Cut	185.00 FL	*185.00 FL
17	2		*REAR BUMPER SENSOR	Damaged (1 PCS ONLY)	360.00 FL	*180.00 FL
18	2		*REAR TAILLAMP -LH/RH	Cracked	790.00 FL	*790.00 FL
19	2		*REAR TAILLAMP CLIP -LH/RH	Necessary	12.00 FL	*12.00 FL
20	1		*REAR PANEL	Dented	560.00 FL	*560.00 FL
21	1		*REAR PANEL TOP GARNISH	Deformed	240.00 FL	*240.00 FL
22	4		*REAR PANEL TOP GARNISH CLIP	Necessary	20.00 FL	*20.00 FL
23	1		*REAR SPARE TYRE BOARD	Cracked	267.00 FL	*267.00 FL
24	2		*REAR FENDER INNER GARNISH -LH/RH	Not Necessary	640.00 FL	*- FL
25	1		*ANTENNA KEY SENSOR	Damaged	161.00 FL	*161.00 FL
26	1		*REAR FLOOR PANEL	Repair	797.00 FL	*- FL
27	1		*REAR EXHAUST	Not Necessary	939.00 FL	*- FL
28	1		*REAR EXHAUST INSULATOR	Not Necessary	135.00 FL	*- FL
29	1		*FRONT BONNET LOCK	Not Necessary	130.00 FL	*- FL
30	1		*FRONT GIRLLE ASSY WITH LOGO AND CHROME GARNISH	Cracked	564.00 FL	*564.00 FL
31	1		*FRONT GRILLE TOP GARNISH	Deformed	135.00 FL	*135.00 FL
32	4		*FRONT GRILLE TOP GARNISH CLIP	Necessary	20.00 FL	*20.00 FL
33	1		*FRONT HEADLAMP -LH/RH	N/S Cut	7,758.00 FL	*3,879.00 FL
34	1		*FRONT BUMPER	Deformed	514.00 FL	*514.00 FL
35	2		*FRONT BUMPER SIDE HOLDER-LH/RH	Necessary	210.00 FL	*210.00 FL
36	10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
37	1		*FRONT BUMPER LOWER GRILLE	Cracked	188.00 FL	*188.00 FL
38	2		*FRONT BUMPER FOGLAMP GARNISH -LH/RH	Not Necessary	354.00 FL	*- FL
39	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	382.00 FL	*- FL
40	1		*FRONT BUMPER FOAM	Deformed	108.00 FL	*108.00 FL
41	1		*FRONT SUPPORT PANEL	Repair	989.00 FL	*- FL
42	1		*CONDENSER	Not Necessary	1,820.00 FL	*- FL
43	2		*CONDENSER SIDE GARNISH -LH/RH (NPA)	Not Necessary	0.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*RADIATOR	Not Necessary	2,169.00 FL	*- FL
45	1		*BRACE PANEL	Bent	155.00 FL	*155.00 FL
46	1		*FRONT NUMBER PLATE WITH CASING	Dented	35.00 FS	*35.00 FS
47	1		*REAR NUMBER PLATE WITH CASING	Not Necessary	35.00 FS	*- FS
48	1		*COOLANT ANY	Necessary	50.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					25,322.00	10,709.00
- List Item Discount on L Items 25.00/25.00% (S\$)					6,300.50	2,658.50
Total Parts (S\$)					19,021.50	8,050.50
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ,CUT /WELD FRONT SUPPORT PANEL ,REAR PANEL ,REAR FLOOR PANEL,REMOVE,REPLACE ACCIDENT PARTS	New	2,200.00	1,600.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,800.00	1,300.00
3	TO REMOVE,REFIX CONDENSER AND REFILL GAS	New	100.00	100.00
4	TO CHECK WIRING (REAR AND FRONT)	New	50.00	50.00
5	TO TUFF KOTE	New	120.00	80.00
6	TO REMOVE,REPLACE REAR BUMPER SENSOR	New	80.00	50.00
7	TO REMOVE,REFIX INNER GARNISH TO FACILITATE REPAIRS	New	150.00	30.00
8	TO REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	New	150.00	30.00
9	TO REMOVE,REFIX REAR EXHAUST PIPE	New	150.00	0.00
10	TO 4 WHEEL ALIGNMENT	New	100.00	0.00
Gross Labour Cost (\$\$)			4,900.00	3,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >