

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21011898/R1VF3E2

Date: 01/12/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210041545
Claimant Vehicle No : FT700L **Insured Vehicle No :** SMZ4301P
Date of Loss: 07/07/2021 Nature of Claim: TP Claim No: 3806905140SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FT700L**
Make & Model: YAMAHA NMAX155, 155cc Engine No: G3L8E0210062
Reg. Date: 07/11/2020 (Man. Year: 2020) Chassis No: MH3SG5680LK031501
Colour: White Odometer: 5700 km
Engine Capacity: 155 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70-13 Rear Tyre Size: 130/70-13
Front Left Side: IRC 3 mm Rear Left Side: IRC 3 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/11/2021
Date Inspected: 25/11/2021 Inspected At: Speedy Motor Cycle Service Centre (HQ)
10 ANG MO KIO IND PARK 2A #05-21
Singapore 568047
Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$11,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WING MIRROR RH	Scratched	0.00 F	*- F
2	1		*HANDLE BAR BALANCER RH	Scratched	0.00 F	*- F
3	1		*HAND BRAKE LEVER	Scratched	0.00 F	*- F
4	1		*REAR BOX	Cracked	0.00 F	*- F
5	1		*RH SIDE VISOR	Scratched	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >