

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011899/KGA3Q2**Date:** 14/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900249114
Claimant Vehicle No :	SJX7839G	Insured Vehicle No :	SJP7317M
Date of Loss:	17/11/2021	Nature of Claim:	TP
		Claim No:	6223825251SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX7839G	Engine No:	A349302
Make & Model:	PERODUA KENARI, 989cc GX (M)	Chassis No:	PM2L902S002123373
Reg. Date:	12/07/2010 (Man. Year: 2009)	Odometer:	105034 km
Colour:	Red		
Engine Capacity:	989 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165/55 R14	Rear Tyre Size:	165/55 R14
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,175.00	1,087.00	88.00	7.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,190.00	1,375.00	815.00	37.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,365.00	2,462.00	903.00	26.84
Approved Total (Overridden) (S\$)		1,950.00		
(S\$)	3,365.00	1,950.00	1,415.00	42.05
+ GST 7.00/7.00% (S\$)	235.55	136.50	99.05	42.05
Nett Amount (S\$)	3,600.55	2,086.50	1,514.05	42.05
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,328.50		

INSPECTION

Date of Assignment:	23/11/2021	Ah Lim Motor Company (AMK)
Date Inspected:	24/11/2021 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING (NPA)	No such part	0.00 F	*- FL
2	1		*TAILGATE	Bent	780.00 F	*780.00 FL
3	1		*TAILGATE KENARI LOGO	Necessary	45.00 F	*45.00 FL
4	1		*TAILGATE PERODUA LOGO	Necessary	55.00 F	*55.00 FL
5	1		*TAILGATE INNER TRIM (NPA)	Serviceable	0.00 F	*- FL
6	1		*TAILGATE LOCK (NPA)	Repair	0.00 F	*- FL
7	1		*TAILGATE RUBBER (NPA)	Serviceable	0.00 F	*- FL
8	1		*REAR BUMPER (NPA)	Repair	0.00 F	*- FL
9	2		*REAR BUMPER LAMP LH & RH (NPA)	Serviceable	0.00 F	*- FL
10	1		*REAR BUMPER LOWER GARNISH (NPA)	Respray	0.00 F	*- FL
11	2		*REAR BUMPER SIDE RETAINER LH & RH (NPA)	Serviceable	0.00 F	*- FL
12	12		*REAR BUMPER CLIPS (NPA)	Not Necessary	0.00 F	*- FL
13	2		*REVERSE SENSOR LH & RH	Scratched	200.00 FS	*200.00 FS
14	2		*REVERSE SENSOR RING (NPA)	Not Necessary	0.00 F	*- FL
15	1		*REAR END PANEL (NPA)	Repair	0.00 F	*- FL
16	1		*REAR END PANEL GARNISH (NPA)	Serviceable	0.00 F	*- FL
17	1		*EXHAUST PIPE TAIL (NPA)	Serviceable	0.00 F	*- FL
18	1		*EXHAUST PIPE TAIL BRACKET (NPA)	Serviceable	0.00 F	*- FL
19	1		*FRONT CROSSMEMBER (NPA)	Repair	0.00 F	*- FL
20	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
21	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
22	1		*NUMBER PLATE	Scratched	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,175.00	1,175.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	88.00
Total Parts (\$\$)	1,175.00	1,087.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	15.00
2	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR WINDSCREEN	New	120.00	120.00
3	TO DISMANTLE ,REPLACE AND REINSTALL UNDERCARRIAGE	New	350.00	0.00
4	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	50.00
5	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
6	TO REALIGN ,DISMANTLE AND REINSTALL /REPLACE EXHAUST PIPE	New	60.00	60.00
7	TO DISMANTLE ALL DAMAGED PATS,TO CUT & WELD REAR END PANEL ,TO KNOCK & REPAIR SPARE TYRE PANEL INNER PANELS AND AFFECTED AREAS TO REFIT LISTED PARTS BACK SAME	New	800.00	500.00
8	TO SPRAY TAILGATE ,REAR BUMPER ,REAR END PANEL	New	700.00	600.00
Gross Labour Cost (\$\$)			2,190.00	1,375.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >