

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EG121011902/EVF3E2

Date: 17/12/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : FBS3609B **Insured Vehicle No :** SJM8837M
Date of Loss: 12/11/2021 Nature of Claim: TP Claim No: CDMPG21002179-001

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBS3609B**
Make & Model: DUCATI MULTISTRADA 1200S, 1.2 Engine No: ZDM1200W4002138
Reg. Date: 31/03/2021 (Man. Year: 2020) Chassis No: ZDM1A00AAMB001860
Colour: Red Odometer: 6563 km
Engine Capacity: 1158 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70Z R19 Rear Tyre Size: 170/60Z R17
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,817.50	4,749.10	3,068.40	39.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,670.00	3,600.00	70.00	1.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,487.50	8,349.10	3,138.40	27.32
+ GST 7.00/7.00% (S\$)	804.13	584.44	219.69	27.32
Nett Amount (S\$)	12,291.63	8,933.54	3,358.09	27.32

INSPECTION

Date of Assignment: 23/11/2021
Date Inspected: 23/11/2021 Inspected At: Wearnes automotive Pte Ltd (HQ)
45 LENG KEE ROAD
Singapore 159103
Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Dec 2021)	
Parts:	N/A	DUCATI MULTISTRADA 1200S 1.2 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBS3609B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE SU	Broken	64.40 FS	*64.40 FS
2	1		*NUMBER PLATE SU	Broken	57.50 FS	*57.50 FS
3	1		*REAR WHEEL RIM	Bent	2,331.80 FS	*2,331.80 FS
4	1		*TRANSFER	Necessary	18.40 FS	*18.40 FS
5	1		*PLATE	Crushed	218.30 FS	*218.30 FS
6	1		*REAR FRAME COMP	Bent	689.20 FS	*689.20 FS
7	1		*REAR FRAME COMP	Bent	689.20 FS	*689.20 FS
8	2		*CLIP NUT	Necessary	11.20 FS	*11.20 FS
9	1		*CUSHION, SEAT	Necessary	2.50 FS	*2.50 FS
10	2		*PLUG	Necessary	4.20 FS	*4.20 FS
11	2		*PLUG, RH	Necessary	15.60 FS	*15.60 FS
12	2		*PLUG	Necessary	15.60 FS	*15.60 FS
13	1		*REAR WHEEL SPIN	Bent	189.80 FS	*189.80 FS
14	1		*REAR SWINGING A	Not Necessary	2,565.00 FS	*- FS
15	1		*AXLE, REAR SWIN	Not Necessary	160.90 FS	*- FS
16	1		*AXLE, REAR SWIN	Not Necessary	160.90 FS	*- FS
17	2		*BEARING	Not Necessary	67.20 FS	*- FS
18	1		*INNER SPACER	Not Necessary	17.80 FS	*- FS
19	1		*SPACER	Not Necessary	27.60 FS	*- FS
20	2		*SEAL RING	Not Necessary	12.20 FS	*- FS
21	2		*BEARING NEEDLE	Not Necessary	37.40 FS	*- FS
22	1		*PAD	Not Necessary	6.20 FS	*- FS
23	12		*SCREW, SPECIAL	Not Necessary	13.20 FS	*- FS
24	1		*CHAIN LINK	Necessary	42.40 FS	*42.40 FS
25	1		*LAMP, LICENSE PLATE	Shorted	59.70 F	*59.70 F
26	4		*SCREW	Necessary	3.60 F	*3.60 F
27	5		*SCREW	Necessary	11.50 F	*11.50 F
28	1		*VALVE, TUBELESS TIRE	Necessary	21.30 F	*21.30 F
29	6		*WHEEL RUNNER BUSH	Necessary	137.40 F	*137.40 F
30	2		*SEAL RING	Necessary	50.20 F	*50.20 F
31	2		*BEARING	Necessary	77.00 F	*77.00 F
32	4		*SCREW	Necessary	5.60 F	*5.60 F
33	1		*SCREW TCEIF M6X25	Necessary	2.70 F	*2.70 F
34	1		*NUMBER PLATE	Broken	30.00 F	*30.00 F

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **7,817.50** **4,749.10**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ACCIDENT DAMAGE ASSESSMENT	New	70.00	0.00
2	NOTES ACC (NPA)	New	0.00	0.00
3	TO REPLACE DAMAGED PARTS CAUS	New	3,600.00	3,600.00
Gross Labour Cost (S\$)			3,670.00	3,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >