

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011903/VEA3Q2**Date:** 12/05/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070114552
Claimant Vehicle No :	SMC552D	Insured Vehicle No :	SBW505R
Date of Loss:	19/11/2021	Nature of Claim:	TP
		Claim No:	4122868242SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC552D	Engine No:	L15B5462848
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK81202474
Reg. Date:	25/06/2018 (Man. Year: 2018)	Odometer:	90679 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/40Z R17	Rear Tyre Size:	215/40Z R17
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,917.84	1,917.20	1,000.64	34.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	590.00	1,960.00	76.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,467.84	2,507.20	2,960.64	54.15
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	5,467.84	2,000.00	3,467.84	63.42
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		2,531.00		
Global Sum Settlement (S\$)		2,530.00		

INSPECTION

Date of Assignment:	23/11/2021		
Date Inspected:	23/11/2021	Inspected At:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808
Estimated Period of Repair:	3.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -RH	Deformed	1,257.60 FL	*1,150.00 FL
2	1		*FRONT DOOR GLASS OUTER MOULDING	Necessary	105.00 FL	*105.00 FL
3	1		*FRONT DOOR HINGES	Serviceable	97.00 FL	*- FL
4	1		*FRONT DOOR INNER BOARD	Cracked	628.50 FL	*628.50 FL
5	1		*FRONT DOOR INNER LOCK	Serviceable	217.90 FL	*- FL
6	1		*FRONT DOOR OUTER HANDLE	Serviceable	92.60 FL	*- FL
7	1		*FRONT DOOR REGULATOR WITH MOTOR	Serviceable	455.60 FL	*- FL
8	1		*FRONT DOOR WEATHERSTRIP	Serviceable	142.60 FL	*- FL
9	1		*FRONT DOOR SIDE MIRROR	Cracked / Distorted	438.00 FL	*438.00 FL
10	1		*FRONT DOOR CHECKER	Serviceable	62.50 FL	*- FL
11	1		*FRONT DOOR BLACK TAPE	Necessary	120.00 FS	*60.00 FS
					Sub Total (\$)	3,617.30 2,381.50
					- List Item Discount on L Items 20.00/20.00% (\$)	699.46 464.30
					Total Parts (\$)	2,917.84 1,917.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS ,TRANSFER ALL FITTINGS TO NEW DOOR	New	200.00	60.00
2	TO APPLY UNDERCOATING	New	150.00	30.00
3	PANEL BEATING	New	1,200.00	200.00
4	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,000.00	300.00
Gross Labour Cost (\$\$)			2,550.00	590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >