

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011905/EUY3N2**Date:** 06/12/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00003942103	
Claimant Vehicle No :	SMH2121A	Insured Vehicle No :	GBH1187Y	
Date of Loss:	15/11/2021	Nature of Claim:	TP	Claim No: SNM21D206610/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH2121A		Engine No:	69700519
Make & Model:	PORSCHE 911, CARRERA		Chassis No:	WPOZZZ99Z7S740074
Reg. Date:	02/03/2007 (Man. Year: 2006)		Odometer:	145023 km
Colour:	Red			
Engine Capacity:	3596 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/30ZR19	Rear Tyre Size:	295/30ZR19
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,087.10	8,916.90	5,170.20	36.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,510.00	750.00	33.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,347.10	10,426.90	5,920.20	36.22
Approved Total (Overridden) (S\$)		8,350.00		
(S\$)	16,347.10	8,350.00	7,997.10	48.92
+ GST 7.00/7.00% (S\$)	1,144.30	584.50	559.80	48.92
Nett Amount (S\$)	17,491.40	8,934.50	8,556.90	48.92

INSPECTION

Date of Assignment:	23/11/2021	
Date Inspected:	24/11/2021	Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub Singapore 608581
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Dec 2021)
Parts:	M1-COUPE	PORSCHE 911 CARRERA (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH2121A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER LH	Dented	9,000.00 FL	*9,000.00 FL
2	1		*REAR FENDER LOWER PROTECTOR FILM LH	Necessary	301.00 FL	*301.00 FL
3	1		*REAR BUMPER	Repair	3,890.00 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	978.00 FL	*- FL
5	1		*ROCKER PANEL LH (NPA)	Repair	0.00 FL	*- FL
6	1		*REAR BUMPER CLIPS	Not Necessary	35.00 FS	*- FS
7	1		*REAR FENDER SEALANT	Necessary	60.00 FS	*40.00 FS
8	1		*REAR WINDOW QUARTER SEALANT	Necessary	60.00 FS	*40.00 FS
9	1		*RIM 19INCH (Local Repair)	Cut	800.00 FS	*200.00 FS
10	1		*REAR TYRES LH (70%)	Torn	380.00 FS	*266.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,504.00	9,847.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,416.90	930.10
Total Parts (\$\$)	14,087.10	8,916.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,000.00	800.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,000.00	500.00
3	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	60.00	50.00
4	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	30.00	30.00
5	TO REMOVE AND REPLACE/REFIXS REAR TYPRES AND WHEEL BALANCING IN ORDER TO REAR BOTH RIM	New	50.00	50.00
6	TO REMOVE AND REFIT/REPLACE REAR DOOR QUARTER WINDOW LH FITTING,TRIMMINGS,GARNISH,WINDOW GLASS	New	120.00	80.00
Gross Labour Cost (\$\$)			2,260.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >