

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011907/KPS3Q2**Date:** 14/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700064702
Claimant Vehicle No :	SCY686D	Insured Vehicle No :	SLR3481M
Date of Loss:	13/11/2021	Nature of Claim:	TP
		Claim No:	0166371127SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCY686D	Engine No:	RB25313580A
Make & Model:	NISSAN SKYLINE, 2.5 250 GT (A)	Chassis No:	ER34018821
Reg. Date:	23/03/1999 (Man. Year: 1999)	Odometer:	383290 km
Colour:	Metallic Grey		
Engine Capacity:	2498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35Z R18	Rear Tyre Size:	255/35Z R18
Front Left Side:	Kumho 8 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 8 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,985.04	5,294.65	690.39	11.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,820.00	2,180.00	640.00	22.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,805.04	7,474.65	1,330.39	15.11
+ GST 7.00/7.00% (S\$)	616.35	523.23	93.12	15.11
Nett Amount (S\$)	9,421.39	7,997.88	1,423.51	15.11
+ Loss of Use (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,905.33		
Global Sum Settlement (S\$)		8,900.00		

INSPECTION

Date of Assignment:	23/11/2021	Lim Tan Motor Pte Ltd (HQ)
Date Inspected:	04/01/2022 Inspected At:	Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care
Estimated Period of Repair:	8.0 days	Singapore 575721

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,086.60 FN	*1,086.60 FN
2	1		*REAR BUMPER REINFORCEMENT	Bent	787.50 FN	*787.50 FN
3	2		*REAR BUMPER RETAINER	Cracked	102.40 FN	*102.40 FN
4	10		*REAR BUMPER CLIP	Necessary	26.00 FN	*26.00 FN
5	1		*REAR END PANEL	Bent	724.90 FN	*724.90 FN
6	1		*N/S TAILLAMP	Buckled	857.60 FN	*857.60 FN
7	1		*TAILLAMP OUTER GARNISH	Broken	397.60 FN	*397.60 FN
8	1		*TAILLAMP PANEL	Bent	285.50 FN	*285.50 FN
9	1		*N/S REAR FENDER	Bent	1,387.30 FN	*1,387.30 FN
10	1		*N/S REAR FENDER INNER MOULDING	Serviceable	767.10 FN	*- FN
11	1		*REAR WINDSCREEN MOULDING	Necessary	183.10 FN	*183.10 FN
12	1		*TUBE REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	6,645.60	5,878.50
- Nett Item Discount on N Items 10.00/10.00% (\$)	660.56	583.85
Total Parts (\$)	5,985.04	5,294.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY AND SPRAY PAINT	New	1,000.00	700.00
2	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
3	TO REMOVE & REFIX REAR CUSHION SEAT & LINING	New	120.00	100.00
4	TO ANTI-RUST	New	80.00	60.00
5	LABOUR CHARGES	New	1,500.00	1,200.00
Gross Labour Cost (\$)			2,820.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >