

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21011909/EUY3E2

Date: 24/02/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00195462000
Claimant Vehicle No: SNA101X Insured Vehicle No: SMF2604J
Date of Loss: 21/11/2021 Nature of Claim: TP Claim No: SNM21D206726/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNA101X
Make & Model: ASTON MARTIN V8 VANTAGE, Engine No: 17795060100329
Reg. Date: 17/03/2021 (Man. Year: 2019) Chassis No: SCFSLGAW5KGN02848
Colour: Yellow Odometer: 4126 km
Engine Capacity: 3982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40Z R20 Rear Tyre Size: 255/40Z R20
Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm
Front Right Side: Pirelli 4 mm Rear Right Side: Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	54,577.30	29,472.39	25,104.91	46.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,860.00	11,660.00	3,200.00	21.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	69,437.30	41,132.39	28,304.91	40.76
+ GST 7.00/7.00% (S\$)	4,860.61	2,879.27	1,981.34	40.76
Nett Amount (S\$)	74,297.91	44,011.66	30,286.25	40.76

INSPECTION

Date of Assignment: 25/11/2021
Date Inspected: 24/11/2021 Inspected At: Wearnes Automotive Pte Ltd (Leng Kee)
45 Leng Kee Road
Singapore 159103
Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Feb 2022)
Parts:	143	ASTON MARTIN V8 VANTAGE (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA101X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE & HOLDER	Not Necessary	120.00 FS	*- FS
2	1		*HEADLAMP LH / RH (NPA)	Not Necessary	0.00 FS	*- FS
3	1		*HOOD ASSEMBLY	Dented	15,392.50 FS	*13,853.25 FS
4	1		*LATCH SECONDARY LH	Not Necessary	228.50 FS	*- FS
5	2		*STRKR SECONDARY	Not Necessary	201.40 FS	*- FS
6	1		*LATCH SECONDARY RH	Not Necessary	228.50 FS	*- FS
7	2		*STRIKER - BONNET	Not Necessary	204.20 FS	*- FS
8	1		*FRT CTR PED LEG FOAM	Not Necessary	235.20 FS	*- FS
9	1		*INTAKE FOAM LH UPPER	Not Necessary	124.70 FS	*- FS
10	1		*INTAKE FOAM RH UPPER	Not Necessary	124.70 FS	*- FS
11	5		*SCRIVET-PACK OF 5	Necessary	13.00 FS	*11.70 FS
12	1		*FRT BMPR ASSY ROW	Cracked	5,787.30 FS	*5,208.57 FS
13	1		*FRONT SPLITTER - BLACK	Cut	4,158.60 FS	*3,742.74 FS
14	9		*SCR M6 X 14 HD INT	Necessary	23.40 FS	*21.06 FS
15	10		*CLIP SPG M6 PK OF 10	Necessary	24.00 FS	*21.60 FS
16	2		*WSHR 25MM X 6.4MM-10	Necessary	2.60 FS	*2.34 FS
17	2		*BOLT M6X35 HEX	Necessary	3.80 FS	*3.42 FS
18	20		*SCREW-M6X20 PACK 20	Necessary	54.00 FS	*48.60 FS
19	10		*RET-GRILLE BMPR (10)	Necessary	12.00 FS	*10.80 FS
20	4		*LAMP ADJUSTER	Not Necessary	292.00 FS	*- FS
21	1		*RAD GRILLE BLACK	Not Necessary	3,791.10 FS	*- FS
22	1		*FRONT CAMERA BEZEL	Necessary	15.30 FS	*13.77 FS
23	1		*HLDR CMR FRT FACING	Necessary	32.80 FS	*29.52 FS
24	1		*IN-GRL PDC HOLDER LH	Necessary	9.90 FS	*8.91 FS
25	1		*IN-GRL PDC HOLDER RH	Necessary	9.90 FS	*8.91 FS
26	20		*SCRIVET-PACK OF 5	Necessary	52.00 FS	*46.80 FS
27	2		*SENSOR PARKING AID	Not Necessary	212.80 FS	*- FS
28	2		*SENSOR PARKING AID	Not Necessary	212.80 FS	*- FS
29	2		*SENSOR PARKING AID	Not Necessary	227.60 FS	*- FS
30	6		*DECOUPLING RING	Not Necessary	235.80 FS	*- FS
31	1		*FRT U/TRAY	Not Necessary	1,098.00 FS	*- FS
32	1		*UTRAY SPPRT BAR	Not Necessary	1,001.10 FS	*- FS
33	1		*CLIP SPG M6 PK OF 10 (10PCS)	Necessary (1Pc Only)	24.00 FS	*2.16 FS
34	20		*SCREW-M6X20 PACK 20	Necessary	54.00 FS	*48.60 FS
35	1		*BADGE ASSY AML	Necessary	1,198.00 FS	*1,078.20 FS
36	1		*PNL H/LAMP MNT LH	Not Necessary	2,315.20 FS	*- FS
37	1		*PNL H/LMP MNT RH	Not Necessary	2,315.20 FS	*- FS
38	2		*BRKT HD/LP NUT PLT	Necessary	45.80 FS	*41.22 FS
39	1		*AUX RAD DUCT RR LH	Not Necessary	943.10 FS	*- FS
40	1		*AUX RAD DUCT RR RH	Not Necessary	943.10 FS	*- FS
41	2		*BUMPER SEAL	Necessary	294.40 FS	*264.96 FS
42	1		*PNL VNT AIR CTR LWR	Not Necessary	592.70 FS	*- FS
43	1		*PNL RAD GRL CTR	Not Necessary	1,351.50 FS	*- FS
44	10		*SCREW&WSHR M6X20 (10)	Necessary	14.00 FS	*12.60 FS
45	1		*PNL VEN AIR CTR UPR	Not Necessary	555.70 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*LWR FRT SPLITTER	Not Necessary	1,589.00 FS	*- FS
47	1		*PNL VEN AIR LH	Not Necessary	741.40 FS	*- FS
48	1		*PNL VEN AIR RH	Not Necessary	741.40 FS	*- FS
49	1		*RAD SUPPORT LWR	Not Necessary	946.10 FS	*- FS
50	1		*PNL H/LAMP MNT LH	Broken	2,315.20 FS	*2,083.68 FS
51	1		*PNL H/LMP MNT RH	Broken	2,315.20 FS	*2,083.68 FS
52	20		*SCREW&WSHR M6X20 (10)	Necessary	28.00 FS	*25.20 FS
53	2		*SENSOR PARKING AID	Shorted	212.80 FS	*191.52 FS
54	2		*SENSOR PARKING AID	Shorted	212.80 FS	*191.52 FS
55	2		*SENSOR PARKING AID	Shorted	227.60 FS	*204.84 FS
56	1		*DECOUPLING RING (12PCS)	Necessary	471.60 FS	*212.22 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	54,577.30	29,472.39
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE BONNET, FRONT BUMPER RADIATOR GRILLE, FRONT BUMPER LOWER SPOILER, HEADLAMP LH / RH, PARKING SENSORS, ETC	New	8,000.00	6,400.00
2	TO SPRAY BONNET, FRONT BUMPER, FRONT SPOILER, ETC	New	5,500.00	3,900.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	1,020.00	1,020.00
4	TO FOCUS HEADLAMP	New	340.00	340.00
Gross Labour Cost (\$\$)			14,860.00	11,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >