

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121011910/GQF3N2**Date:** 23/03/2022REFERENCE

| | | | |
|------------------------------|--------------------------|-----------------------------|---------------|
| Handling Insurer: | ERGO Insurance Pte. Ltd. | Policy No: | DMPG21013546 |
| Claimant Vehicle No : | GBG3196M | Insured Vehicle No : | SMQ3530Z |
| Date of Loss: | 18/11/2021 | Nature of Claim: | TP |
| | | Claim No: | CDMPG21002215 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|---------------|
| Reg No: | GBG3196M | | |
| Make & Model: | TOYOTA HIACE, 3.0 D DX (A) | Engine No: | 1KD2634360 |
| Reg. Date: | 24/07/2017 (Man. Year: 2016) | Chassis No: | KDH2015023538 |
| Colour: | Yellow | Odometer: | 166956 km |
| Engine Capacity: | 2982 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 195 R15 | Rear Tyre Size: | 195 R15 |
| Front Left Side: | Austone 6 mm | Rear Left Side: | Austone 6 mm |
| Front Right Side: | Austone 6 mm | Rear Right Side: | Austone 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 4,545.00 | 2,654.80 | 1,890.20 | 41.59 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,730.00 | 970.00 | 760.00 | 43.93 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 6,275.00 | 3,624.80 | 2,650.20 | 42.23 |
| Approved Total (Overridden) (S\$) | | 2,800.00 | | |
| Nett Amount (S\$) | 6,275.00 | 2,800.00 | 3,475.00 | 55.38 |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 23/11/2021 | Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT Singapore 417883 |
| Date Inspected: | 24/11/2021 Inspected At: | |
| Estimated Period of Repair: | 4.0 days | |

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 23 Mar 2022) |
| Parts: | 213 | TOYOTA HIACE 3.0 D DX (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for GBG3196M) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------------|---------------|------------|--------------|
| 1 | 1 | | *REAR TAILGATE | Buckled | 1,950.90 F | *1,929.10 FL |
| 2 | 1 | | *REAR TAILGATE INNER LOCK | Cut | 359.00 F | *359.00 FL |
| 3 | 1 | | *REAR TAILGATE RUBBER | Not Necessary | 426.70 F | *- FL |
| 4 | 1 | | *REAR TAILGATE TOYOTA LOGO MOTIF | Necessary | 167.00 F | *167.00 FL |
| 5 | 1 | | *REAR BUMPER | Deformed | 465.00 F | *465.00 FL |
| 6 | 1 | | *REAR BUMPER STEP PANEL | Bent | 262.30 F | *262.30 FL |
| 7 | 1 | | *REAR END PANEL OUTER | Repair | 566.10 F | *- FL |
| 8 | 1 | | *REAR TAILGATE 70KM/H STICKER | Necessary | 15.00 FS | *10.00 FS |
| 9 | 1 | | *REAR TAILGATE 8 PAX STICKER | Necessary | 15.00 FS | *10.00 FS |
| 10 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 48.00 FS | *48.00 FS |
| 11 | 1 | | *REAR BUMPER REVERSE SENSOR | Damaged | 220.00 FS | *200.00 FS |
| 12 | 1 | | *REAR END PANEL SEALANT | Not Necessary | 50.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (\$\$) | 4,545.00 | 3,450.40 |
| - List Item Discount on L Items 0.00/25.00% (\$\$) | 0.00 | 795.60 |
| Total Parts (\$\$) | 4,545.00 | 2,654.80 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM | New | 80.00 | 60.00 |
| 2 | REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE REPAIRS | New | 120.00 | 120.00 |
| 3 | REMOVE AND REFIX REAR BUMPER REVERSE SENSOR | New | 80.00 | 40.00 |
| 4 | LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS | New | 800.00 | 400.00 |
| 5 | TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS | New | 600.00 | 350.00 |
| 6 | TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA | New | 50.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 1,730.00 | 970.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >