

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21011912/AQY3E2

Date: 08/02/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00017302101
Claimant Vehicle No : SMM2061M **Insured Vehicle No :** SJY5789A
Date of Loss: 18/11/2021 Nature of Claim: TP Claim No: SNM21D206677/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM2061M**
Make & Model: TOYOTA HARRIER, 2.0 (A) Engine No: 8ARZ157230
Reg. Date: 21/06/2019 (Man. Year: 2019) Chassis No: JTEZB3GH00J004456
Colour: Black Odometer: 84182 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,926.67	6,395.97	7,530.70	54.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,070.00	1,500.00	1,570.00	51.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,996.67	7,895.97	9,100.70	53.54
Approved Total (Overridden) (\$\$)		6,300.00		
Nett Amount (\$\$)	16,996.67	6,300.00	10,696.67	62.93

INSPECTION

Date of Assignment: 20/01/2022
Date Inspected: 24/11/2021 Inspected At: Hong Auto Services (Kaki Bukit)
2 Kaki Bukit Avenue 2, #01-28 Kaki Bukit Auto Hub
Singapore 417921
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2022)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM2061M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	855.82 FL	*855.82 FL
2	1		*FRONT BUMPER SIDE GRILLE - RH	Not Necessary	198.35 FL	*- FL
3	1		*FRONT BUMPER PDC SENSOR - RH	Damaged	441.32 FL	*265.00 FL
4	1		*FRONT BUMPER LOWER SPOILER	Not Necessary	441.35 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP - RH	Not Necessary	238.68 FL	*- FL
6	1		*FRONT BUMPER FOG LAMP GRILLE	Not Necessary	89.95 FL	*- FL
7	1		*FRONT BUMPER TOW COVER	Not Necessary	48.82 FL	*- FL
8	1		*FRONT BUMPER SPONGE	Cracked	115.36 FL	*115.36 FL
9	1		*FRONT BUMPER REINFORCEMENT	Dented	538.13 FL	*538.13 FL
10	1		*FRONT BUMPER SIDE BEAM - RH	Bent	121.60 FL	*121.60 FL
11	1		*FRONT BUMPER SIDE RETAINERS - L/R	O/S Damaged	86.90 FL	*43.45 FL
12	1		*FRONT BUMPER UNDERCOVER	Not Necessary	260.95 FL	*- FL
13	1		*FRONT BONNET	Not Necessary	1,053.35 FL	*- FL
14	1		*FRONT BONNET SEAL	Not Necessary	110.20 FL	*- FL
15	10		*FRONT BONNET INSULATOR CLIPS	Not Necessary	55.00 FL	*- FL
16	1		*FRONT FENDER - RH	Distorted	776.81 FL	*776.81 FL
17	1		*FRONT FENDER TOP 1/4 GARNISH	Not Necessary	86.95 FL	*- FL
18	1		*FRONT FENDER INNER SHIELD	Deformed	358.02 FL	*226.00 FL
19	15		*FRONT FENDER INNER SHIELD CLIP	Necessary	82.50 FL	*30.00 FL
20	1		*FRONT FENDER STAY	Bent	110.65 FL	*110.65 FL
21	1		*FRONT DOOR - RH	Repair	1,455.90 FL	*- FL
22	1		*FRONT DOOR CHROME MOULDING	Not Necessary	281.60 FL	*- FL
23	1		*FRONT GRILLE ASSY	Not Necessary	761.04 FL	*- FL
24	6		*FRONT GRILLE CLIPS	Not Necessary	33.00 FL	*- FL
25	1		*FRONT HEADLAMP ASSY - RH	Cracked	3,513.15 FL	*3,513.15 FL
26	1		*FRONT SUPPORT PANEL	Not Necessary	856.92 FL	*- FL
27	1		*FRONT SHOCK ABSORBER - RH	Not Necessary	481.50 FL	*- FL
28	1		*FRONT LOWER ARM	Bent	760.90 FL	*493.00 FL
29	1		*FRONT LOWER ARM BALL JOINT	Not Necessary	288.40 FL	*- FL
30	1		*FRONT KNUCKLE ARM	Not Necessary	548.05 FL	*- FL
31	1		*FRONT ANTI ROLL BAR	Not Necessary	481.60 FL	*- FL
32	1		*FRONT ANTI ROLL BAR LINK	Not Necessary	161.20 FL	*- FL
33	1		*FRONT WHEEL HUB BEARING	Damaged	451.90 FL	*451.90 FL
34	1		*FRONT SPORT WHEEL - RH	Cut	1,615.93 FN	*500.00 F
35	1		*WASHER TANK	Deformed	280.42 FL	*280.42 FL
36	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
37	1		*FRONT TYRE - RH	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	18,437.22	8,351.29
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,106.57	1,955.32
- Nett Item Discount on N Items 25.00/0.00% (\$\$)	403.98	0.00
Total Parts (\$\$)	13,926.67	6,395.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	30.00
2	TO REMOVE, REFIX FRONT UNDERCARRIAGE	New	400.00	150.00
3	TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
4	TO RESPRAY UNDERCOATING	New	100.00	40.00
5	TO RESPRAY PAINTING & ETC	New	1,200.00	600.00
6	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS	New	1,200.00	600.00
Gross Labour Cost (\$)			3,070.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >