

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011914/EEA3Q2**Date:** 16/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900007277
Claimant Vehicle No :	SLW1792C	Insured Vehicle No :	SMH3166P
Date of Loss:	21/11/2021	Nature of Claim:	TP
		Claim No:	5810762728SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW1792C	Engine No:	G4FGHH691458
Make & Model:	KIA CERATO K3, 1.6 (A)	Chassis No:	KNAFX411MJ5761496
Reg. Date:	31/01/2018 (Man. Year: 2017)	Odometer:	63700 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,039.00	1,392.80	646.20	31.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	960.00	750.00	43.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,749.00	2,352.80	1,396.20	37.24
+ GST 7.00/7.00% (S\$)	262.43	164.70	97.73	37.24
Nett Amount (S\$)	4,011.43	2,517.50	1,493.93	37.24
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
Nett Liability (S\$)		2,838.50		

INSPECTION

Date of Assignment:	23/11/2021	
Date Inspected:	29/11/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*COVER -RR BUMPER	Dented	688.00 FS	*550.40 FS
3	1		*COVER -RR BUMPER ,CTR	Cut	315.00 FS	*252.00 FS
4	1		*BEAM -RR BUMPER	Broken	318.00 FS	*254.40 FS
5	1		*STAY -RR BUMPER RH	Not Necessary	120.00 FS	*- FS
6	1		*STAY -RR BUMPER LH	Bent	120.00 FS	*96.00 FS
7	1		*BRACKET -RR BEAM UPE MTG	Not Necessary	3.00 FS	*- FS
8	1		*BRACKET -RR BEAM UPE MTG, RH	Not Necessary	3.00 FS	*- FS
9	1		*BRACKET -RR BUMPER SIDE MTG ,LH	Not Necessary	33.00 FS	*- FS
10	1		*BRACKET -RR BUMPER SIDE MTG ,RH	Not Necessary	29.00 FS	*- FS
11	1		*LOGO ASSY -KIA SUB	Not Necessary	37.00 FS	*- FS
12	1		*EMBLEM -CERATO	Not Necessary	35.00 FS	*- FS
13	1		*TRIM -TRANSVERSE RR	Not Necessary	58.00 FS	*- FS
14	1		*C&C LOGO	Not Necessary	40.00 FS	*- FS
15	1		*SET OF REVERSE SENSOR	Broken	220.00 FS	*220.00 FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	2,039.00 1,392.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR BUMPER ,REPAIR BOOTLID	New	800.00	400.00
2	SPRAY PAINT FOR REAR BUMPER ,BOOTLID	New	700.00	350.00
3	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRICAL CONTROL SYSTEM	New	120.00	120.00
Gross Labour Cost (\$\$)			1,710.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >