

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Chou Kin Sang (zhao Qingsheng)	Cust No/Name /Chou Kin Sang (ZHAO QINGSHENG)
BLK 43 JALAN TIGA #12-20 SINGAPORE 390043	Reg No/Reg Date SLW1792C / 31/01/201
Contact No Mobile: 92383178	Date In/Mileage / 0
	Chassis No KNAFX411MJ5761496
	Engine No G4FGHH691458
	Make/Model KIA/CERATO K3 1.6 A EX CAP
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	23/11/2021/ 15:39	TLC	442 / CocoLu	42801			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								800.00
RENEW REAR BUMPER, REPAIR BOOTLID								
E PNT98000								700.00
SPRAY PAINT FOR REAR BUMPER, BOOTLID								
E PNT88000								60.00
REMOVE & INSTALL PARKING SENSOR								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								40.00
C&C LOGO								
M SUNDRY								20.00
Sundry								
M COVER-RR BUMPER					1.00	688.00	00.00	688.00
M COVER-RR BUMPER,CTR					1.00	315.00	00.00	315.00
M BEAM-RR BUMPER					1.00	318.00	00.00	318.00
M STAY-RR BUMPER RH					1.00	120.00	00.00	120.00
M STAY-RR BUMPER LH					1.00	120.00	00.00	120.00
M BRACKET-RR BEAM UPR MTG					1.00	3.00	00.00	3.00
M BRACKET-RR BEAM UPR MTG,RH					1.00	3.00	00.00	3.00
M BRACKET-RR BUMPER SIDE MTG,LH					1.00	33.00	00.00	33.00
M BRACKET-RR BUMPER SIDE MTG,RH					1.00	29.00	00.00	29.00
M LOGO ASSY-KIA SUB					1.00	37.00	00.00	37.00
M EMBLEM-CERATO					1.00	35.00	00.00	35.00
M TRIM-TRANSVERSE RR					1.00	58.00	00.00	58.00

Confirm & accepted by

	Nett	3,529.00
7% GST on	3529.00	247.03
Total Payable		3,776.03

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.