

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011918/RTY3Q2**Date:** 09/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00092922102
Claimant Vehicle No : SKZ4724B **Insured Vehicle No :** GBC2035Y
 Date of Loss: 22/11/2021 Nature of Claim: TP Claim No: SNM21D206743/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ4724B**
 Make & Model: HONDA ODYSSEY, 2.4 (A) Engine No: K24W72010617
 Reg. Date: 25/01/2016 (Man. Year: 2015) Chassis No: JHMRC1890GC201450
 Colour: Grey Odometer: 69660 km
 Engine Capacity: 2356 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,636.51	2,017.41	1,619.10	44.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,090.00	6,830.00	3,260.00	32.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,726.51	8,847.41	4,879.10	35.55
+ GST 7.00/7.00% (S\$)	960.86	619.32	341.54	35.55
Nett Amount (S\$)	14,687.37	9,466.73	5,220.64	35.55

INSPECTION

Date of Assignment: 03/03/2022
 Date Inspected: 06/12/2021 Inspected At: Kah Motor Co Sdn Bhd (HQ)
 6A MANDAI ESTATE, SINGAPORE 729903
 Singapore 729903
 Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2022)
Parts: M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ4724B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL COMPL.SLIDE DOOR	Buckled	800.25 FS	*800.25 FS
2	1		*TAPE SETL.RR.DOOR SASH INNER	Necessary	45.67 FS	*45.67 FS
3	1		*MOLDING ASSYL.RR.DOOR	Necessary	55.65 FS	*55.65 FS
4	1		*GARNISH ASSYL.SIDE DOOR LWR	Necessary	217.57 FS	*217.57 FS
5	1		*FENDERL.RR INNER	Serviceable	93.00 FS	*- FS
6	1		*PANEL SET,L.RR.OUTER	Buckled	747.97 FS	*747.97 FS
7	1		*MOLDING ASSYL.QTR WINDSHIELD	Necessary	87.75 FS	*87.75 FS
8	1		*COVER COMPL.SLIDE DR CTR RAIL	Not Necessary	131.62 FS	*- FS
9	1		*FACE ,L.RR.BUMPER GARNISH	Not Necessary	61.42 FS	*- FS
10	1		*FACERR.BUMPER	Repair	454.57 FS	*- FS
11	1		*FACER.RR.BUMPER GARNISH	Not Necessary	61.42 FS	*- FS
12	1		*SPACERR.RR.BUMPER SIDE	Not Necessary	15.30 FS	*- FS
13	1		*SPACERL.RR.BUMPER SIDE	Necessary	15.30 FS	*15.30 FS
14	1		*CLIP BUMPER (10 PCS)	Necessary	17.25 FS	*17.25 FS
15	1		*DISK ALUMINIUM WHEEL 17X7J	Repair	731.77 FS	*- FS
16	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
Total Parts (S\$)					3,636.51	2,017.41

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	180.00	150.00
2	REMOVE & RENEW REVERSE SENSORS	New	180.00	150.00
3	REMOVE & TRANSFER ITEMS TO NEW RR L SLIDING DR	New	650.00	650.00
4	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	325.00
5	PERFORM SETTING ON MULTI NEW CAMERA & SMART	New	450.00	325.00
6	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	650.00	325.00
7	REPLACE RR .L DOOR QTR GLASS	New	650.00	325.00
8	BODY JOINT SEALANT QTR GLASS	New	100.00	80.00
9	BODY JOINT SEALANT LHR FENDER	New	100.00	80.00
10	CUT & RENEW RR L FENDER STRAIGHTEN INNER PANEL	New	3,500.00	2,600.00
11	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	3,000.00	1,820.00
12	WHEEL ALIGNMENT	New	180.00	0.00
Gross Labour Cost (\$)			10,090.00	6,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >