

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21011922/AGA3Q2**Date:** 19/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800072863
<b>Claimant Vehicle No :</b>	SLX6974G	<b>Insured Vehicle No :</b>	GBF923G
Date of Loss:	16/11/2021	Nature of Claim:	TP
		Claim No:	0034427179SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLX6974G</b>	Engine No:	LEB5591752
Make & Model:	HONDA FREED, 1.5 (A)	Chassis No:	GB71060158
Reg. Date:	06/04/2018 (Man. Year: 2018)	Odometer:	257551 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,084.50	3,472.72	4,611.78	57.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	1,870.00	1,610.00	46.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,564.50</b>	<b>5,342.72</b>	<b>6,221.78</b>	<b>53.80</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,564.50</b>	<b>4,200.00</b>	<b>7,364.50</b>	<b>63.68</b>
<b>+ Loss of Use (9.0 x S\$50.00/day) (S\$)</b>		450.00		
		<b>4,650.00</b>		
		<b>Nett Liability (S\$)</b>		

INSPECTION

Date of Assignment:	21/11/2021	
Date Inspected:	16/11/2021	Inspected At: Advance Auto Garage 10 Kaki Bukit Road 2, #01-21 First East Centre Singapore 417868
Estimated Period of Repair:	6.0 days	

**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	828.90 F	*828.90 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*REAR BUMPER SIDE HOLDER RH	Damaged	49.80 F	*49.80 FL
4	1		*TAILLAMP RH	Cracked	629.10 F	*629.10 FL
5	1		*REAR RH FENDER	Distorted	912.40 F	*912.40 FL
6	1		*REAR RH FENDER INNER SHIELD	Not Necessary	140.20 F	*- FL
7	1		*REAR RH FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
8	1		*REAR RH FENDER INNER TRIM BOARD	Not Necessary	586.40 F	*- FL
9	1		*REAR RH FENDER INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
10	1		*REAR RH FENDER TOP COVER	Not Necessary	398.90 F	*- FL
11	1		*REAR RH FENDER GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
12	1		*REAR RH FENDER AIR GRILLE	Cracked	40.50 F	*40.50 FL
13	1		*SLIDING DOOR RH	Dented	1,153.40 F	*1,153.40 FL
14	1		*SLIDING DOOR WEATHERSTRIPE RH	Not Necessary	185.40 F	*- FL
15	1		*SLIDING DOOR LOCK RH	Not Necessary	262.40 F	*- FL
16	1		*REAR RH WHEEL RIM	Bent	300.00 FS	*150.00 FS
17	1		*REAR RH WHEEL RIM COVER	Cut	150.00 FS	*100.00 FS
18	1		*REAR RH TYRE	Not Necessary	250.00 FS	*- FS
19	1		*REAR AXLE	Not Necessary	1,450.90 F	*- FL
20	1		*REAR RH WHEEL HUB C/W BEARING	Damaged	326.80 F	*326.80 FL
21	1		*REAR RH SHOCK ABSORBER	Not Necessary	289.40 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>8,084.50</b>	<b>4,260.90</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$)</b>	0.00	788.18
<b>Total Parts (\$)</b>	<b>8,084.50</b>	<b>3,472.72</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,200.00	600.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	80.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	150.00	80.00
7	TO REMOVE FENDER GLASS	New	100.00	50.00
8	TO REMOVE REAR UNDERCARRIAGE	New	380.00	100.00
9	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
			<b>Gross Labour Cost (\$)</b>	<b>3,480.00</b>
				<b>1,870.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >