



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2108774
3 ANSON ROAD #16-00	INV Date	20/12/2021
SPRINGLEAF TOWER	Reference	CC3/CTI21011924/Krs3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SMX 6857A
Insured Veh.	SBY 223T
Claim No.	SNM21D206329/C02
Policy No.	DMPCSNW00196462000
Accident Date	03/11/2021
Inspection Date	22/11/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC3/CTI21011924/Krs3q2 Date: 20/12/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBY 223T	Veh. Inspected	SMX 6857A
Policy No.	DMPCSNW00196462000	Coverage (\$)	0.00
Claim No.	SNM21D206329/C02	Excess (\$)	0.00
Assign From		Assign Date	22/11/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	JTDKB3FU703091426	Colour	METALLIC SILVER
Odometer	85272 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	SAILUN	9 mm
L/H Front Tyre	195/65 R15	SAILUN	9 mm
R/H Rear Tyre	195/65 R15	DUNLOP	3 mm
L/H Rear Tyre	195/65 R15	DUNLOP	3 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/11/2021	Inspection Date	22/11/2021
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMX 6857A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER ,REAR BUMPER	BUCKLED	485.60	485.60
1	REINFORCEMENT SUB-ASSY ,REAR BUMPER	BENT	332.70	332.70
1	COVER ,REAR BUMPER ,LOWER	SERVICEABLE	22.00	-
1	GUARD ,REAR BUMPER ,CENTER	SERVICEABLE	374.50	-
1	RETAINER ,REAR BUMPER SIDE ,LH	SERVICEABLE	132.60	-
1	RETAINER ,REAR BUMPER SIDE ,RH	SERVICEABLE	132.60	-
1	COVER ,DECK TRIM ,REAR	SERVICEABLE	126.70	-
1	PANEL SUB-ASSY ,BODY LOWER BACK	TO REPAIR SEE LABOUR	651.00	-
1	COVER ,FRONT BUMPER	BUCKLED	521.00	521.00
1	UNIT ASSY ,HEADLAMP ,LH	SERVICEABLE	2,637.60	-
1	UNIT ASSY ,HEADLAMP ,RH	MTG CRACKED	2,637.60	2,637.60
1	HOOD SUB-ASSY	BENT	983.10	983.10
1	HINGE ASSY ,HOOD ,LH	TO REPAIR SEE LABOUR	58.90	-
1	HINGE ASSY ,HOOD ,RH	TO REPAIR SEE LABOUR	58.90	-
1	LOCK ASSY ,HOOD	TO REPAIR SEE LABOUR	135.00	-
1	BRACKET ,FRONT BUMPER EXTENSION MOUNTING	TO REPAIR SEE LABOUR	110.50	-
1	REINFORCEMENT SUB-ASSY ,FRONT BUMPER	TO REPAIR SEE LABOUR	716.60	-
1	ABSORBER ,FRONT BUMPER ENERGY	TO REPAIR SEE LABOUR	80.20	-
1	GRILL SUB-ASSY ,RADIATOR	DENTED / CRACKED	422.50	422.50
1	GRILLE ,RADIATOR ,LOWER NO.1	SERVICEABLE	178.60	-
1	EMBLEM ASSY ,RADIATOR GRILLE	MISSING	105.80	105.80
	LESS 25% DISCOUNT		-2,726.00	-1,372.07
			8,178.00	4,116.23
SPECIAL NETT ITEMS				
1	REAR SPOILER CLIP (SN)	NOT NECESSARY	70.00	-

Report Ref No. CC3/CTI21011924/Krs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	95.00	50.00
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	180.00	-
1	SET REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	85.00	-
1	END PANEL TRIM CLIP (SN)	NOT NECESSARY	65.00	-
1	SET BUMPER CLIP FRT (SN)	NECESSARY	95.00	50.00
1	FRONT NUMBER PLATE WITH MOULDING (SN)	BENT	200.00	45.00
1	REAR NUMBER PLATE WITH MOULDING (SN)	SERVICEABLE	200.00	-
1	SET FRONT BUMPER RETAINER CLIP (SN)	NOT NECESSARY	85.00	-
			1,775.00	145.00
	LABOUR			
	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	300.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY ,BODY LOWER BACK,HINGE ASSY ,HOOD ,LH,HINGE ASSY ,HOOD ,RH ,LOCK ASSY ,HOOD ,BRACKET ,FRONT BUMPER EXTENSION MOUNTING ,REINFORCEMENT SUB-ASSY ,FRONT BUMPER AND ABSORBER ,FRONT BUMPER ENERGY.		2,200.00	600.00
	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT ELECTRICAL WIRING ,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	480.00	-
	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	480.00	-
	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT VACUUM AND CHARGE-IN -GAS.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-

Report Ref No. CC3/CTI21011924/Krs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS .		250.00	30.00
	TOWING FEES.	NOT NECESSARY	150.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		2,200.00	660.00
	TO REINSTALL REAR BUMPER PARKING SENSOR .		170.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	30.00
	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING .	NOT NECESSARY	220.00	-
	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR .	NOT NECESSARY	170.00	-
	TO LIFT -UP/OUT ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS - MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR.	NOT NECESSARY	380.00	-
	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS.	NOT NECESSARY	380.00	-
			10,290.00	1,370.00
	GRAND TOTAL		20,243.00	5,631.23
RECOMMENDED COST OF REPAIRS				5,631.23

Report Ref No. CC3/CT121011924/Krs3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMX 6857A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMX 6857A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMX 6857A

RE-INSPECTION

