

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21011925/VVF3N2**Date:** 01/12/2021REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MS009843

Claimant Vehicle No : SH9249Z**Insured Vehicle No :** GBH9199K

Date of Loss: 23/11/2021

Nature of Claim: TP Claim No: M2105422

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SH9249Z**

Make & Model: HYUNDAI I40, 1.7 D CRDi (A)

Engine No: D4FDHU723436

Reg. Date: 20/12/2017 (Man. Year: 2016)

Chassis No: KMHLB41UMHU098814

Colour: Blue

Odometer: 567230 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size: 206/60R16

Rear Tyre Size: 206/60R16

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,320.42	4,097.22	1,223.20	22.99
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,680.00	1,140.00	540.00	32.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,011.42	5,248.22	1,763.20	25.15
Approved Total (Overridden) (S\$)		4,050.00		
(S\$)	7,011.42	4,050.00	2,961.42	42.24
+ GST 7.00/7.00% (S\$)	490.80	283.50	207.30	42.24
Nett Amount (S\$)	7,502.22	4,333.50	3,168.72	42.24

INSPECTION

Date of Assignment: 23/11/2021

Date Inspected: 24/11/2021 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Dec 2021)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH9249Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BOOTLID COVER	Deformed	2,609.80 FL	-	*2,609.80 FL
2	1		*BOOTLID HINGE LH	Serviceable	142.30 FL	-	*- FL
3	1		*BOOTLID HINGE RH	Serviceable	142.30 FL	-	*- FL
4	1		*BOOTLID EMBLEM - I40	Necessary	85.00 FL	-	*85.00 FL
5	1		*BOOTLID EMBLEM - CRDI	Necessary	52.40 FL	-	*52.40 FL
6	1		*BOOTLID EMBLEM - H	Necessary	63.10 FL	-	*63.10 FL
7	1		*BOOTLID COMFORTDELGRO LOGO	Necessary	30.00 F	-	*30.00 FS
8	1		*BOOTLID TEL. NOS STICKER	Necessary	30.00 F	-	*30.00 FS
9	1		*BOOTLID APPS LOGO	Necessary	40.00 F	-	*40.00 FS
10	1		*REAR BUMPER ASSY	Cut	553.00 FL	-	*553.00 FL
11	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
12	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	-	*228.00 FL
13	1		*REAR BUMPER SPONGE	Cut	119.50 FL	-	*119.50 FL
14	1		*REAR BUMPER REINFORCEMENT	Cut	428.40 FL	-	*428.40 FL
15	1		*REAR BUMPER MAT	Necessary	50.00 F	-	*50.00 FS
16	1		*REAR BUMPER REFLECTOR RH	Missing	32.00 FL	-	*32.00 FL
17	1		*REVERSE SENSOR	Cut	135.70 F	-	*135.70 FS
18	1		*BOOTLID LAMP RH	Serviceable	622.20 FL	-	*- FL
19	1		*BOOTLID LAMP LH	Serviceable	622.20 FL	-	*- FL
20	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FL	-	*50.00 FL
21	2		*REAR FENDER ADVERTISEMENT LOGO	Necessary	200.00 FL	-	*200.00 FL
Supplementary #1							
22	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Dented	160.60 FL	-	*160.60 FL
23	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Dented	160.60 FL	-	*160.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,579.10	5,050.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,258.68	952.88
Total Parts (\$\$)	5,320.42	4,097.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	900.00	560.00
2	SPRAYPAINT	New	600.00	500.00
3	CHECK WIRING	New	50.00	20.00
4	TUFF KOTE	New	50.00	30.00
5	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (\$\$)			1,680.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >