

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

India International Insurance Pte Ltd  
64 Cecil Street, #04-00 IOB Building  
Singapore 049711

**Our File No:** CS/III21011929/EQF3N2**Date:** 07/02/2022**REFERENCE**

|                   |                                         |                  |                  |           |                 |
|-------------------|-----------------------------------------|------------------|------------------|-----------|-----------------|
| Insured/Claimant: | PAN PACIFIC VAN & TRUCK LEASING PTE LTD | Policy No:       | D19MFL0005549_02 |           |                 |
| Date of Loss:     | 20/11/2021                              | Nature of Claim: | OD               | Claim No: | MFL2021D0005099 |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |  |             |                   |
|-----------------------------|-----------------------------------|--|-------------|-------------------|
| Reg No:                     | <b>GBK3085D</b>                   |  | Engine No:  | YD25069265B       |
| Make & Model:               | NISSAN NV350, 2.5 (A)             |  | Chassis No: | JN1MC2E26Z0032087 |
| Reg. Date:                  | 30/03/2020 (Man. Year: 2019)      |  | Odometer:   | 60385 km          |
| Colour:                     | White                             |  |             |                   |
| Engine Capacity:            | 2488 cc                           |  |             |                   |
| Market Value/New Car Price: | S\$70,000.00                      |  |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |  |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 195R15C       | Rear Tyre Size:  | 195R15C       |
| Front Left Side:  | Triangle 4 mm | Rear Left Side:  | Triangle 4 mm |
| Front Right Side: | Triangle 4 mm | Rear Right Side: | Triangle 4 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 16,407.80         | 7,327.50          | 9,080.30          | 55.34         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 4,700.00          | 2,310.00          | 2,390.00          | 50.85         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>21,107.80</b>  | <b>9,637.50</b>   | <b>11,470.30</b>  | <b>54.34</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>8,500.00</b>   |                   |               |
| <b>- Excess (S\$)</b>                    | 1,500.00          | 1,500.00          | 0.00              | 0.00          |
| <b>(S\$)</b>                             | 19,607.80         | 7,000.00          | 12,607.80         | 64.30         |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 1,372.55          | 490.00            | 882.55            | 64.30         |
| <b>Nett Amount (S\$)</b>                 | <b>20,980.35</b>  | <b>7,490.00</b>   | <b>13,490.35</b>  | <b>64.30</b>  |

**INSPECTION**

|                             |                          |                                                                                                                          |
|-----------------------------|--------------------------|--------------------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 24/11/2021               | Efficient Motor & Engineering Works Pte Ltd (HQ)<br>56 Loyang Way #06-07, Loyang Enterprise Building<br>Singapore 508775 |
| Date Inspected:             | 25/11/2021 Inspected At: |                                                                                                                          |
| Estimated Period of Repair: | 8.0 days                 |                                                                                                                          |

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                        |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 05 Feb 2022)                                                                                                                                             |                                                        |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | NISSAN NV350 2.5 (A) (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                      |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for GBK3085D)                                                                                                                                    |                                                        |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                        |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                        |

### Recommended Parts

| No. | Qty | Part No. | Particulars                             | Condition     | Repairer's | Amount      |
|-----|-----|----------|-----------------------------------------|---------------|------------|-------------|
| 1   | 1   |          | *FRONT BUMPER (WCP)                     | Broken        | 280.00 F   | *280.00 F   |
| 2   | 2   |          | *FRONT BUMPER SIDE RETAINER LH/RH (WCP) | Broken        | 150.00 F   | *150.00 F   |
| 3   | 1   |          | *FRONT BUMPER CENTER GRILLE (WCP)       | Broken        | 380.00 F   | *380.00 F   |
| 4   | 1   |          | *FRONT BUMPER REINFORCEMENT (WCP)       | Not Necessary | 350.00 F   | *- F        |
| 5   | 1   |          | *FRONT BUMPER CENTRE BEAM (WCP)         | Not Necessary | 95.00 F    | *- F        |
| 6   | 2   |          | *FRONT REINFORCEMENT BRKT LH/RH (WCP)   | Not Necessary | 100.00 F   | *- F        |
| 7   | 1   |          | *AIR GUIDE LOWER (WCP)                  | Not Necessary | 48.00 F    | *- F        |
| 8   | 1   |          | *FRONT GRILLE (WCP)                     | Broken        | 400.00 F   | *400.00 F   |
| 9   | 1   |          | *FRONT GRILLE LOGO (WCP)                | Missing       | 50.00 F    | *50.00 F    |
| 10  | 2   |          | *HEADLAMP UNIT LH/RH (WCP)              | Broken        | 390.00 F   | *390.00 F   |
| 11  | 1   |          | *FRONT PANEL (WCP)                      | Dented        | 650.00 F   | *650.00 F   |
| 12  | 1   |          | *FRONT PANEL LOWER CENTER (WCP)         | Dented        | 75.00 F    | *75.00 F    |
| 13  | 1   |          | *AUTO TRANSMISSION COOLER PIPE (WCP)    | Not Necessary | 560.00 F   | *- F        |
| 14  | 1   |          | *AIR BAG SENSOR CENTRE (WCP)            | Not Necessary | 380.00 F   | *- F        |
| 15  | 1   |          | *OIL COOLER (WCP)                       | Dented        | 580.00 F   | *580.00 F   |
| 16  | 1   |          | *OIL COOLER GARNISH (WCP)               | Broken        | 135.00 F   | *135.00 F   |
| 17  | 1   |          | *WIPER MOTOR (WCP)                      | Not Necessary | 165.00 F   | *- F        |
| 18  | 1   |          | *WIPER LINK ASSY (WCP)                  | Not Necessary | 220.00 F   | *- F        |
| 19  | 1   |          | *AIR CON BLOWER MOTOR ASSY (WCP)        | Broken        | 600.00 F   | *600.00 F   |
| 20  | 1   |          | *HEATER UNIT ASSY (WCP)                 | Broken        | 1,800.00 F | *1,800.00 F |
| 21  | 1   |          | *RADIATOR (WCP)                         | Not Necessary | 650.00 F   | *- F        |
| 22  | 1   |          | *RADIATOR FAN BLADE (WCP)               | Not Necessary | 250.00 F   | *- F        |
| 23  | 1   |          | *RADIATOR FAN COWLING (WCP)             | Not Necessary | 150.00 F   | *- F        |
| 24  | 1   |          | *CONDENSER & FAN ASSY (WCP)             | Not Necessary | 1,000.00 F | *- F        |
| 25  | 1   |          | *AIR CON LIQUID PIPE (WCP)              | Not Necessary | 320.00 F   | *- F        |
| 26  | 1   |          | *FRONT WINDSCREEN GLASS MOULDING (WCP)  | Necessary     | 50.00 F    | *50.00 F    |
| 27  | 1   |          | *WIPER PANEL COVER (WCP)                | Crushed       | 180.00 F   | *180.00 F   |
| 28  | 1   |          | *DASHBOARD (WCP)                        | Not Necessary | 700.00 F   | *- F        |
| 29  | 1   |          | *DASHBOARD REINFORCEMENT (WCP)          | Not Necessary | 400.00 F   | *- F        |
| 30  | 1   |          | *TOWING COVER (WCP)                     | Crushed       | 20.00 F    | *20.00 F    |
| 31  | 1   |          | *ABS PUMP (WCP)                         | Not Necessary | 1,800.00 F | *- F        |
| 32  | 4   |          | *ABS PUMP PIPE (WCP)                    | Not Necessary | 380.00 F   | *- F        |
| 33  | 1   |          | *HEATER HOSE INLET (WCP)                | Not Necessary | 70.00 F    | *- F        |
| 34  | 1   |          | *HEATER HOSE OUTLET (WCP)               | Not Necessary | 70.00 F    | *- F        |
| 35  | 1   |          | *AIR CON SUCTION HOSE (WCP)             | Bent          | 220.00 F   | *220.00 F   |
| 36  | 1   |          | *AIR CON DISCHARGE HOSE (WCP)           | Bent          | 250.00 F   | *250.00 F   |
| 37  | 1   |          | *FRONT FOG LAMP GARNISH LH/RH (WCP)     | N/s Cut       | 130.00 F   | *65.00 F    |
| 38  | 1   |          | *DRIER RECEIVER (WCP)                   | Not Necessary | 250.00 F   | *- F        |
| 39  | 1   |          | *FRT RH CORNER PANE (WCP)               | Dented        | 200.00 F   | *200.00 F   |
| 40  | 1   |          | *SET FRONT BUMPER CLIPS                 | Necessary     | 50.00 FS   | *30.00 FS   |
| 41  | 1   |          | *SET FRONT GRILLE CLIPS                 | Necessary     | 50.00 FS   | *15.00 FS   |
| 42  | 2   |          | *BRAKE FLUID                            | Necessary     | 100.00 FS  | *20.00 FS   |
| 43  | 1   |          | *WINDSCREEN SEALANT                     | Necessary     | 80.00 FS   | *40.00 FS   |
| 44  | 1   |          | *WINDSCREEN INNER SEAL                  | Necessary     | 30.00 FS   | *30.00 FS   |
| 45  | 1   |          | *WINDSCREEN IU BRACKET                  | Necessary     | 20.00 FS   | *20.00 FS   |
| 46  | 1   |          | *TRANSMISSION FLUID                     | Necessary     | 80.00 FS   | *30.00 FS   |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                  | Condition | Repairer's                                      | Amount           |
|-----|-----|----------|------------------------------|-----------|-------------------------------------------------|------------------|
| 47  | 1   |          | *COOLANT                     | Necessary | 50.00 FS                                        | *20.00 FS        |
|     |     |          | F=Franchise part. S=SpcNett. |           |                                                 |                  |
|     |     |          |                              |           | <b>Sub Total (S\$)</b>                          | <b>14,958.00</b> |
|     |     |          |                              |           | <b>+ Margin on L,N Items 10.00/10.00% (S\$)</b> | <b>6,680.00</b>  |
|     |     |          |                              |           |                                                 | 1,449.80         |
|     |     |          |                              |           |                                                 | 647.50           |
|     |     |          |                              |           | <b>Total Parts (S\$)</b>                        | <b>16,407.80</b> |
|     |     |          |                              |           |                                                 | <b>7,327.50</b>  |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                   | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                               |          |                 |                 |
| 1                               | TO CUT & WELD ON DAMAGED FRONT PANELS AND TO REPLACE FRONT DAMAGED PARTS      | New      | 2,000.00        | 1,000.00        |
| 2                               | TO REMOVE AND REFIT FRONT WINDSCREEN TO FACILITATE REPAIRS                    | New      | 150.00          | 120.00          |
| 3                               | TO REMOVE AND REFIT FRONT DASHBOARD TO FACILITATE REPAIRS                     | New      | 250.00          | 200.00          |
| 4                               | TO CHECK AND RECTIFY LIGHTING AND WIRE HARNESS                                | New      | 80.00           | 30.00           |
| 5                               | TO SPRAY PAINT FRONT PANEL,FRONT BUMPER,FRONT CORNER PANEL AND AFFECTED AREAS | New      | 2,000.00        | 900.00          |
| 6                               | TOCONDUCT DIAGNOSTIC SCAN AND RESET FAULT CODE                                | New      | 150.00          | 0.00            |
| 7                               | TOWING FEE                                                                    | New      | 70.00           | 60.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                                               |          | <b>4,700.00</b> | <b>2,310.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >