

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO21011930/Kuf3e2	
	50 RAFFLES PLAC TOWER SINGAPO		Date:	29/11/2021		
				Code:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBH 7600G	Veh. Inspected	t	CB 6361Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2103464/THE	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		24/11/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE (M)	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	KDH2015000273	Colour		BLUE	
	Odometer	816762 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15X8	WINDFORCE		9 mm	
	L/H Front Tyre	195 R15X8	WINDFORCE		9 mm	
	R/H Rear Tyre	195 R15X8	DELIUM		2 mm	
	L/H Rear Tyre	195 R15X8	DELIUM		2 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORT					
5.	General Information					
	Accident Date	23/11/2021	Inspect Date /	Time	24/11/2021 (11:00 AM)	
	Survey held at	Survey held at EM SOLUTION PTE LTD				
	160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$6,000					
5b.		Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					

Report Ref No. CS3/SMO21011930/Kuf3e2

Inspected By

KONG SENG CHEONG

K.K.LAU CPT(RET)

Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser