

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21011931/ETF3N2**Date:** 22/12/2021**REFERENCE**

Insured/Claimant:	XIAO XIAO	Policy No:	7210090696		
Date of Loss:	22/11/2021	Nature of Claim:	OD	Claim No:	1604225981SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB2914Z		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11DC2875
Reg. Date:	12/08/2021 (Man. Year: 2021)	Chassis No:	GF7W0701261
Colour:	Black	Odometer:	3886 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$126,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,110.68	1,882.56	1,228.12	39.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,290.00	1,965.00	1,325.00	40.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,400.68	3,847.56	2,553.12	39.89
+ GST 7.00/7.00% (S\$)	448.05	269.33	178.72	39.89
Nett Amount (S\$)	6,848.73	4,116.89	2,731.84	39.89

INSPECTION

Date of Assignment: 24/11/2021

Date Inspected: 01/12/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REINFORCEMENT,RR BUMPER,LH	Not Necessary	79.00 FL	*- FL
2	1		*REINFORCEMENT,RR BUMPER,RH	Not Necessary	79.00 FL	*- FL
3	1		*BRKT,R/BMPR FACE SIDE,RH	Not Necessary	12.00 FL	*- FL
4	1		*BRKT,R/BMPR FACE SIDE,LH	Not Necessary	12.00 FL	*- FL
5	1		*FACE,RR BUMPER	Dented	811.00 FL	*811.00 FL
6	1		*EXTENSION,RR BUMPER	Cut	289.00 FL	*289.00 FL
7	2		*CLIP,ENG ROOM COVER	Not Necessary	4.00 FL	*- FL
8	2		*CLIP,ENG ROOM COVER	Not Necessary	4.00 FL	*- FL
9	1		*CLIP,RR BUMPER	Necessary	6.00 FL	*6.00 FL
10	1		*W/STRIP,TAILGATE OPENING	Not Necessary	213.00 FL	*- FL
11	1		*PANEL ASSY,TAILGATE	Dented	989.00 FL	*989.00 FL
12	1		*GARNISH,TAILGATE	Not Necessary	496.00 FL	*- FL
13	2		*STOPPER,WINDSHIELD GLASS	Necessary	6.00 FL	*6.00 FL
14	1		*DAM,TAILGATE LWR	Necessary	41.00 FL	*41.00 FL
15	2		*DAM,TAILGATE SIDE	Necessary	54.00 FL	*54.00 FL
16	4		*FASTENER,WINDSHIELD	Necessary	24.00 FL	*24.00 FL
17	1		*DAM,TAILGATE,UPR	Necessary	13.00 FL	*13.00 FL
18	1		*GLASS,TAILGATE WINDOW	Not Necessary	657.00 FL	*- FL
19	1		*MARK,OUTLANDER	Necessary	95.00 FL	*95.00 FL
20	1		*EMBLEM MIVEC TECHNOLOGY	Necessary	30.00 FS	*30.00 FS
21	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
22	1		*C&C EMBLEM	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,004.00	2,418.00
- List Item Discount on L Items 23.00/23.00% (\$)	893.32	535.44
Total Parts (\$)	3,110.68	1,882.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER, TAILGATE & AFFECTED AREA. REPAIR ON END PANEL	New	1,800.00	675.00
2	PAINT WORK ON REAR BUMPER & TAILGATE	New	700.00	700.00
3	REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR	New	240.00	240.00
4	TO APPLY WINDSCREEN SEALANT	New	80.00	80.00
5	REMOVE & INSTALL REAR PARKING ASSIST	New	80.00	80.00
6	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	120.00	0.00
7	TO APPLY SEALANT ON AFFECTED AREA	New	80.00	40.00
8	PERFORM RUST PREVENTION	New	40.00	0.00
9	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
10	TO CARRY OUT DIAGNOCTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
Gross Labour Cost (\$\$)			3,290.00	1,965.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >