1/25/22, 11:39 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG21011932/AQCN2

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 **Date:** 25/01/2022

REFERENCE

Insured/Claimant: SEBASTIAN JOSE ALUKKAL Policy No:

Date of Loss: 21/11/2021 Nature of Claim: OD Claim No: 1741235423SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMW9546H

Make & Model: AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A) Engine No: CZDC15468

Reg. Date: 18/12/2020 (Man. Year: 2020) Chassis No: WAUZZZF30M1040028

Colour: Blue Odometer: 11827 km

Engine Capacity: 1395 cc
Market Value/New Car Price: \$\$160,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50R19 Rear Tyre Size: 235/50R19
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,562.00	3,346.40	2,215.60	39.83
Miscellaneous Items		0.00	0.00	0.00	
Labour		6,092.00	1,672.00	4,420.00	72.55
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	11,654.00	5,018.40	6,635.60	56.94
	- Excess (S\$)	800.00	800.00	0.00	0.00
	(S\$)	10,854.00	4,218.40	6,635.60	61.14
	+ GST 7.00/7.00% (S\$)	759.78	295.29	464.49	61.13
	Nett Amount (S\$)	11,613.78	4,513.69	7,100.09	61.14

INSPECTION

Date of Assignment: 24/11/2021

Date Inspected: Premium Automobiles Pte Ltd (UBI)

23/11/2021 Inspected At: 55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR-RH	Buckled	2,816.00 FS	*2,252.80 FS
2	1		*FRONT DOOR OUTER SEAL-RH	Necessary	116.00 FS	*132.80 FS
3	1		*FRONT DOOR CATCH-RH	Not Necessary	120.00 FS	*- FS
4	1		*FRONT WINDOW GUIDE TRIM-RH	Deformed	257.00 FS	*205.20 FS
5	1		*FRONT DOOR B-PILLAR TRIM-RH	Deformed	112.00 FS	*89.20 FS
6	1		*FRONT WINDOW ALUMINIUM SLOT SEAL TRIM-RH OUTER	Not Necessary	224.00 FS	*- FS
7	1		*FRONT DOOR WINDOW GUIDE-RH	Deformed	433.00 FS	*346.40 FS
8	1		*TYRE PRESSURE DATA PLATE	Necessary	30.00 FS	*24.00 FS
9	1		*FRONT DOOR WINDOW-RH	Not Necessary	242.00 FS	*- FS
10	1		*REAR DOOR B-PILLAR TRIM RH	Not Necessary	117.00 FS	*-FS
11	1		*REAR WINDOW GUIDE TRIM-RH	Not Necessary	152.00 FS	*- FS
12	1		*REAR WINDOW ALUMINIUM SLOT SEAL TRIM-RH OUTER	Not Necessary	273.00 FS	*- FS
13	1		*FRONT DOOR LOWER COVER-RH	Necessary	370.00 FS	*296.00 FS
14	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Fra	nchise	part. S=Spc	Nett.		r	
				Total Parts (S\$)	5,562.00	3,346.40
			Report was unsubmitted during this print-c	out.	P	

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER MODULE DEVICES.INSPECT FOR DAMAGES	New	400.00	280.00
2	TO INSTALL SOLAR FILM FOR RHS FRONT DOOR WINDOW GLASS	New	400.00	0.00
3	TO DISMANTLE AND RENEW RHS FRONT DOOR.TO REPAIR RHS REAR DOOR.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
4	TO RESPRAY RHS FRONT DOOR,DOOR COVER,RHS ROOF CHANNEL AND RHS REAR DOOR	New	3,500.00	700.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labou	r Cost (S\$)	6,092.00	1,672.00
	Report was unsubmitted during this	print-out		

< END OF ESTIMATES >