

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21011935/EVF3E2

Date: 11/01/2022

REFERENCE

Insured/Claimant:	HOE KEE KOK	Policy No:	7210120663		
Date of Loss:	22/11/2021	Nature of Claim:	OD	Claim No:	6189052007SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDV7000R		
Make & Model:	KIA STONIC, 998cc (A)	Engine No:	G3LEMP192652
Reg. Date:	12/10/2021 (Man. Year: 2021)	Chassis No:	KNAD6817VN6617641
Colour:	Grey	Odometer:	868 km
Engine Capacity:	998 cc		
Market Value/New Car Price:	S\$100,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Kumho 4 mm	Rear Left Side:	Kumho 4 mm
Front Right Side:	Kumho 4 mm	Rear Right Side:	Kumho 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,026.00	4,028.40	1,997.60	33.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,450.00	600.00	29.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,076.00	5,478.40	2,597.60	32.16
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	6,976.00	4,378.40	2,597.60	37.24
+ GST 7.00/7.00% (S\$)	488.32	306.49	181.83	37.24
Nett Amount (S\$)	7,464.32	4,684.89	2,779.43	37.24

INSPECTION

Date of Assignment:	24/11/2021	
Date Inspected:	24/11/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH FRAME	Broken	50.00 FS	*50.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
3	1		*EMBLEM-KIA -- 86300H8400	Necessary	41.00 F	*41.00 FL
4	1		*PANEL ASSY-HOOD -- 66400H8430	Dented	1,135.00 F	*1,135.00 FL
5	1		*COVER-FR BUMPER, UPR	Broken	476.00 F	*476.00 FL
6	1		*COVER-FR BUMPER, LWR	Broken	367.00 F	*367.00 FL
7	1		*GRILLE-FRONT BUMPER	Broken	247.00 F	*247.00 FL
8	1		*AIR DUCT-FR BUMPER, RH	Not Necessary	38.00 F	*- FL
9	1		*GRILLE ASSY-RADIATOR	Not Necessary	324.00 F	*- FL
10	1		*CAP-FRONT HOOK	Crushed	5.00 F	*5.00 FL
11	1		*SKID PLATE-FR BUMPER	Cut	55.00 F	*55.00 FL
12	1		*LIP-FR BUMPER	Not Necessary	42.00 F	*- FL
13	1		*STRIP-FR BUMPER	Not Necessary	27.00 F	*- FL
14	1		*COVER-RADIATOR GRILLE UPR	Broken	46.00 F	*46.00 FL
15	1		*MOULDING-FRONT BUMPER A/INTAKE	Broken	61.00 F	*61.00 FL
16	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	98.00 F	*98.00 FL
17	1		*COVER-BLANKING FRT FOG, RH	Cut	28.00 F	*28.00 FL
18	1		*STIFFNER-FR BPR LWR	Not Necessary	123.00 F	*- FL
19	1		*BRACKET-FR BUMPER SIDE, RH	Not Necessary	13.00 F	*- FL
20	1		*BEAM COMPLETE-FR BUMPER	Dented	544.00 F	*544.00 FL
21	1		*LATCH ASSY-HOOD	Not Necessary	101.00 F	*- FL
22	1		*GARNISH ASSY-FNDR SIDE, RH	Not Necessary	45.00 F	*- FL
23	1		*GUARD ASSY-FRONT WHEEL, RH	Not Necessary	56.00 F	*- FL
24	1		*LAMP ASSY-HEAD, RH	Cut	1,845.00 F	*1,845.00 FL
25	1		*HORN ASSY-LOW PITCH	Not Necessary	64.00 F	*- FL
26	1		*RESERVOIR & PUMP ASSY-WASHER	Not Necessary	152.00 F	*- FL
27	1		*GUARD-AIR	Not Necessary	23.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,026.00	5,018.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	989.60
Total Parts (\$\$)	6,026.00	4,028.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, BONNET	New	1,200.00	600.00
2	SPRAY PAINT FOR FRT BUMPER, BONNET	New	700.00	700.00
3	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
Gross Labour Cost (\$\$)			2,050.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >