

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info
HOE KEE KOK	Cust No/Name LCV14625/HOE KEE KOK
106 GERALD DRIVE	Reg No/Reg Date SDV7000R / 12/10/202
#01-11	Date In/Mileage / 0
SINGAPORE 798595	Chassis No KNAD6817VN6617641
Contact No	Engine No G3LEMP192652
	Make/Model KIA/STONIC 1.0 A PE E02R
	Colour/Trim URG URBAN GREEN / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV14625	CRDVCH	24/11/2021/ 11:16	BLC	442 / CocoLu	42850			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, BONNET,								600 1200.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, BONNET								700.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								120.00
M SUNDRY FRT NUMBER PLATE WITH FRAME								50.00
M SUNDRY Sundry								20.00
M SUNDRY EMBLEM-KIA -- 86300H8400								
M SUNDRY PANEL ASSY-HOOD -- 66400H8430								
M COVER-FR BUMPER UPR					1.00	476.00	00.00	476.00
M COVER-FR BUMPER, LWR					1.00	367.00	00.00	367.00
M GRILLE-FRONT BUMPER					1.00	247.00	00.00	247.00
M AIR DUCT-FR BUMPER, RH					1.00	38.00	00.00	38.00
M GRILLE ASSY-RADIATOR					1.00	324.00	00.00	324.00
M CAP-FRONT HOOK					1.00	5.00	00.00	5.00
M SKID PLATE-FR BUMPER					1.00	55.00	00.00	55.00
M LIP-FR BUMPER					1.00	42.00	00.00	42.00
M STRIP-FR BUMPER					1.00	27.00	00.00	27.00
M COVER-RADIATOR GRILLE UPR					1.00	46.00	00.00	46.00
M MOULDING-FRONT BUMPER A/INTAKE					1.00	61.00	00.00	61.00
M ABSORBER-FRONT BUMPER ENERGY					1.00	98.00	00.00	98.00
M COVER-BLANKING FRT FOG, RH					1.00	28.00	00.00	28.00
M STIFFNER-FR BPR LWR					1.00	123.00	00.00	123.00
M BRACKET-FR BUMPER SIDE, RH					1.00	13.00	00.00	13.00
M BEAM COMPLETE-FR BUMPER					1.00	544.00	00.00	544.00
M LATCH ASSY-HOOD					1.00	101.00	00.00	101.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
HOE KEE KOK	Cust No/Name LCV14625/HOE KEE KOK
106 GERALD DRIVE	Reg No/Reg Date SDV7000R / 12/10/202
#01-11	Date In/Mileage / 0
SINGAPORE 798595	Chassis No KNAD6817VN6617641
Contact No	Engine No G3LEMP192652
	Make/Model KIA/STONIC 1.0 A PE E02R
	Colour/Trim URG URBAN GREEN / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV14625	CRDVCH	24/11/2021/ 11:16	BLC	442 / CocoLu	42850
Description of Goods / Services	Qty	Unit Price	Disc%	Amount	
M GARNISH ASSY-FNDR SIDE,RH ? X nn	1.00	45.00	00.00	45.00	
M GUARD ASSY-FRONT WHEEL,RH X nn	1.00	56.00	00.00	56.00	
M LAMP ASSY-HEAD,RH ✓ cut ? X nn	1.00	1845.00	00.00	1845.00	✓
M HORN ASSY-LOW PITCH ? X nn	1.00	64.00	00.00	64.00	
M RESERVOIR & PUMP ASSY-WASHER ? X nn	1.00	152.00	00.00	152.00	
M GUARD-AIR ? X nn	1.00	23.00	00.00	23.00	

Estimate

Steve (LKK)
 24/11/21, 2.00pm

00-N-1 AL
 Excess - ?
 P/P

My Bel sy
 4 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

7% GST on **Nett** 6,900.00 **6,900.00**
483.00
Total Payable 7,383.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.