



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 7878Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	DEFORMED	1,970.00	1,970.00
4	FRT BUMPER PARKING SENSOR	DAMAGED (2 PCS ONLY)	1,272.00	636.00
1	FRT BUMPER SPONGE	CRACKED	115.00	115.00
1	FRONT NO PLATE HOLDER	DEFORMED	113.00	113.00
1	FRT GRILLE	CRACKED	880.00	880.00
2	HEADLAMP	N/S CRACKED	4,456.00	2,228.00
1	FRT BUMPER REINFORCEMENT	NOT NECESSARY	1,685.00	-
1	FRT BUMPER CENTRE GRILLE	CUT	120.00	120.00
1	REAR BUMPER	DEFORMED	2,007.00	2,007.00
4	REAR BUMPER REVERSE SENSOR	NOT NECESSARY	1,272.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	835.00	-
	LESS 10% DISCOUNT		-1,472.50	-806.90
			13,252.50	7,262.10
	<u>SPECIAL NETT ITEMS</u>			
1	FRT NO PLATE (SN)	CRACKED	40.00	40.00
			40.00	40.00
	<u>LABOUR</u>			
	PANEL BEATING.		1,000.00	500.00
	SPRAY PAINTING.		1,000.00	600.00
	WIRING.		30.00	30.00
			2,030.00	1,130.00
	GRAND TOTAL		15,322.50	8,432.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,700.00

Report Ref No. CS/AGI21011936/Avf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.