

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011937/TQY3Q2**Date:** 14/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00114812102

Claimant Vehicle No : GBK8051T **Insured Vehicle No :** GBD4150D

Date of Loss: 18/11/2021 Nature of Claim: TP Claim No: SNM21D206695/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK8051T**

Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KDB042593

Reg. Date: 26/11/2020 (Man. Year: 2020) Chassis No: JTFAT35Y60K215440

Colour: White Odometer: 11698 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R15 Rear Tyre Size: 155 R12 (D)

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,475.27	1,643.90	11,831.37	87.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,230.00	2,350.00	2,880.00	55.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,705.27	3,993.90	14,711.37	78.65
Approved Total (Overridden) (\$\$)		3,200.00		
(\$\$)	18,705.27	3,200.00	15,505.27	82.89
+ GST 7.00/7.00% (\$\$)	1,309.37	224.00	1,085.37	82.89
Nett Amount (\$\$)	20,014.64	3,424.00	16,590.64	82.89

INSPECTION

Date of Assignment: 25/11/2021

Date Inspected: 27/12/2021 Inspected At: Efficient Motor & Engineering Works Pte Ltd (HQ)
56 Loyang Way #06-07, Loyang Enterprise Building
Singapore 508775

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Mar 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK8051T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	748.90 FL	*- FL
2	2		*FRONT BUMPER BRACKET LH/RH	Not Necessary	439.00 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	182.20 FL	*- FL
4	1		*FRONT GRILLE	Cracked	595.20 FL	*438.85 FL
5	1		*FRONT GRILLE LOGO	Necessary	70.50 FL	*70.50 FL
6	2		*HEADLAMP LH/RH	Not Necessary	2,357.40 FL	*- FL
7	1		*FRONT PANEL LOWER	Bent	980.00 FL	*980.00 FL
8	1		*FRONT WIPER PANEL	Bent	650.00 FL	*445.35 FL
9	1		*FRONT EMBLEM DYNA	Necessary	70.50 FL	*70.50 FL
10	1		*REAR TAILGATE REINFORCEMENT	Repair	5,500.00 FL	*- FL
11	1		*TAILGATE HYDRAULIC LH	Not Necessary	3,200.00 FL	*- FL
12	1		*REAR LOWER REINFORCEMENT	Not Necessary	2,800.00 FL	*- FL
13	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
14	1		*SET FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
15	1		*70KM/H STICKER	Necessary	50.00 FS	*30.00 FS
16	1		*WINDSCREEN SEALANT	Necessary	80.00 FS	*50.00 FS
17	1		*WINDSCREEN INNER SEAL	Necessary	30.00 FS	*20.00 FS
18	1		*WINDSCREEN IU BRACKET	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	17,873.70	2,145.20
- List Item Discount on L Items 25.00/25.00% (S\$)	4,398.43	501.30
Total Parts (S\$)	13,475.27	1,643.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT & WELD ON DAMAGED PANELS ,FRONT PANEL AND TO PANEL BEAT AND REPLACE DAMAGED PARTS	New	2,500.00	1,200.00
2	TO CHECK AND RECTIFY LIGHTING AND WIRE HARNESS	New	80.00	30.00
3	TO SPRAY PAINT FRONT BUMPER ,FRONT PANEL LOWER ,WIPER PANEL & FRONT GRILLE AND AFFECTED AREAS	New	2,000.00	1,000.00
4	TO REMOVE AND INSTALL REAR TAILGATE AND CONDUCT LOAD TEST	New	500.00	0.00
5	TO REMOVE AND REPLACE FRONT WINDSCREEN	New	150.00	120.00
Gross Labour Cost (\$)			5,230.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >