

ASS. REC. BY: Tan J REF: CS/C7121011933/Ty 3.

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. **SNM21D206695/C02**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vch: _____

(Policy Condition)

Remark: The vch had commenced its repair at the time of inspection.

Val. or Market Value: 882K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: 8 days Res.: Yes or No

Lum Sum: _____ % WP

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Date / Time: _____ Action / Instruction: _____

Veh No: GAK8051T Yr Regn: 2029 Nov

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Dyna 2982

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 11698 T/Radio: Insured / Std / NI / NA

Eng/No: 3TEA+35Y60K215440

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Drake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRIM / STD A/Rim or

Tyre Size: F: 195/75R15

R: 155/R12 (D)

BS / SUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front: 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 27/12/21

Survey held at: Efficient Motor

Des. of Damages: FR / Rear / O/S / N/S / W/O / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

29/12/21 @ 2.22pm revised to Jacqueline Tan via Merimen.

we will be advising our Principal a cost of repair of LS \$3200/- with 8 days of repair, subject to their approval. (Red \$15505.28, 83%)

Date/Time, File Pass (V) ☐ : Prelim. Report

08/03 Typist

Date/Time, File Return to?

2)

Report Formed:

MER-TP

Lump Sum / RS in:

3200

Days of Repair: 8

Recovery No. of Trip: 1

Add Fee:

☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Other (\$

Survey Fee:

Transportation:

LS + RS: \$

Photos

Quoted

Total

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

37 LOYANG WAY, SINGAPORE 508734

VEHICLE NO : GBK8051T
MAKE & MODEL : TOYOTA DYNA 150 5MT
CHASSIS NO : JTFAT35Y60K215440

DATE:
CLAIM TYPE :
D.O.A:

23 Dec 2021
OD CLAIM
18 Nov 2021

TO : CHINA TAIPING

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	FRONT BUMPER		\$ 748.90	\$ Rp 748.90
2	2	FRONT BUMPER BRACKET LH/RH		\$ 219.50	\$ X 439.00
3	1	FRONT BUMPER REINFORCEMENT		\$ 182.20	\$ X 182.20
4	1	FRONT GRILLE		\$ 595.20	\$ any 595.20
5	1	FRONT GRILLE LOGO		\$ 70.50	\$ net 70.50
6	2	HEADLAMP LH/RH		\$ 1,178.70	\$ X 2,357.40
7	1	FRONT PANEL LOWER		\$ 980.00	\$ be 980.00
8	1	FRONT WIPER PANEL		\$ 650.00	\$ bt 650.00
9	1	FRONT EMBLEM DYNA		\$ 70.50	\$ net 70.50
10	1	REAR TAILGATE REINFORCEMENT		\$ 5,500.00	\$ XK 5,500.00
11	1	TAILGATE HYDRAULIC LH		\$ 3,200.00	\$? 3,200.00
12	1	REAR LOWER REINFORCEMENT		\$ 2,800.00	\$ X 2,800.00
13	0	0		\$ -	\$ -
14	0	0		\$ -	\$ -
				\$ 16,195.50	\$ 17,593.70

TOTAL PRICE	\$ 17,593.70
LESS 25%	\$ 4,398.43
SUB TOTAL PRICE	\$ 13,195.28

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	FRONT BUMPER CLIPS SET		\$ 50.00	\$ X 50.00
2	1	FRONT GRILLE CLIPS SET		\$ 50.00	\$ 20 net 50.00
3	1	70KM/H STICKER		\$ 50.00	\$ 20 net 50.00
4	1	WINDSCREEN SEALANT		\$ 80.00	\$ 50 net 80.00
5	1	WINDSCREEN INNER SEAL		\$ 30.00	\$ 20 net 30.00
6	1	WINDSCREEN IU BRACKET		\$ 20.00	\$ net 20.00
7					\$ -
8					\$ -
TOTAL S/NETT				\$ 280.00	\$ 280.00

Labour Charges

1	To cut & weld on damaged panels, front panel and to panel beat and replace damaged parts	\$	2,500.00	1200
2	To check and rectify lightng and wire harness	\$	80.00	30.
3	To spray paint front bumper, front panel lower, wiper panel, front grille and affected areas	\$	2,000.00	1000
5	To remove and install rear tailgate and conduct load test	\$	500.00	200 ? plus
6	To remove and replace front windscreen	\$	150.00	120

TOTAL LABOUR

\$ 5,230.00

Total Cost of Repairs

\$ 18,705.28

(Total parts + Total S/Nett + Total Labour Cost)

Tanpin 9795749
WP' 27/12/2012 4pm
Tanpin @ 16hant.com
Resurvey new parts.
8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: