

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21011938/Eqy3e2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 01/12/2021 SINGAPORE 068811 ATTN: TEO KITTY Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SH 7727Z SMH 8396J Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. S1M03MQW Excess (\$) 0.00 **TEO KITTY Assign Date** 24/11/2021 Assign From **Vehicle Particulars & Condition** 2. TOYOTA C-HR Make & Model 1797 c.c HIDDEN 2019 Engine No. Year of Reg. ZYX102117539 **GREY** Chassis No. Colour 47422 KM Odometer Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 215/60 R17 HABILEAD 5 mm 215/60 R17 **HABILEAD** L/H Front Tyre 5 mm 215/60 R17 **HABILEAD** R/H Rear Tyre 5 mm HABILEAD L/H Rear Tyre 215/60 R17 5 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. 5. **General Information** 22/11/2021 29/11/2021 (01:26 PM) Inspect Date / Time Accident Date 21 toh guan road east toh guan centre #01-16/17 Survey held at Repairer LAY AUTO GARAGE PTE LTD 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

Report Ref No. CS3/ASM21011938/Eqy3e2

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

CHEN TSUE YEE

Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

3 Working Days