

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011939/KEA3Q2**Date:** 20/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070125308
Claimant Vehicle No :	SKG8341X	Insured Vehicle No :	SMU7832E
Date of Loss:	20/11/2021	Nature of Claim:	TP
		Claim No:	3653319612SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG8341X	Engine No:	4GR0300171
Make & Model:	TOYOTA MARK X, 2.5 (A)	Chassis No:	GRX1203024475
Reg. Date:	26/04/2007 (Man. Year: 2007)	Odometer:	220723 km
Colour:	Metallic Silver		
Engine Capacity:	2499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,492.53	8,142.18	1,350.35	14.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,220.00	2,460.00	760.00	23.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,712.53	10,602.18	2,110.35	16.60
Approved Total (Overridden) (S\$)		8,450.00		
(S\$)	12,712.53	8,450.00	4,262.53	33.53
+ GST 7.00/7.00% (S\$)	889.88	591.50	298.38	33.53
Nett Amount (S\$)	13,602.41	9,041.50	4,560.91	33.53
+ Car Rental (11.0 x S\$100.00/day) (S\$)		1,100.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,143.50		
Global Sum Settlement (S\$)		10,140.00		

INSPECTION

Date of Assignment:	24/11/2021	
Date Inspected:	24/11/2021	Inspected At: Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	9.0 days	

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Missing	567.80 FL	*567.80 FL
2	2		*REAR BUMPER TOWING COVERS	Missing	32.00 FL	*32.00 FL
3	1		*REAR BUMPER RETAINER LH	Cracked	87.10 FL	*87.10 FL
4	1		*REAR BUMPER RETAINER RH	Cracked	87.10 FL	*87.10 FL
5	2		*REAR BUMPER BRACKETS	Bent / Dented	231.00 FL	*231.00 FL
6	1		*REAR END PANEL	Bent	604.40 FL	*580.40 FL
7	1		*END PANEL TOP GARNISH	Dented	193.20 FL	*193.20 FL
8	1		*SPARE TYRE FLOOR PANEL	Repair	522.80 FL	*- FL
9	1		*SPARE TYRE FLOOR BOARD	Deformed	143.50 FL	*143.50 FL
10	1		*SPARE TYRE TOOLS BOARD	Mtg Cracked	432.10 FL	*432.10 FL
11	1		*BOOTLID	Bent	853.20 FL	*853.20 FL
12	1		*BOOTLID CHROME MOULDING	Dented	380.60 FL	*380.60 FL
13	1		*TOYOTA LOGO	Necessary	49.25 FL	*49.25 FL
14	1		*MARK EMBLEM	Necessary	45.04 FL	*45.04 FL
15	1		*X EMBLEM	Necessary	39.42 FL	*39.42 FL
16	1		*BOOTLID HINGE LH	Repair	102.71 FL	*- FL
17	1		*BOOTLID HINGE RH	Repair	102.71 FL	*- FL
18	1		*BOOTLID DAMPER LH	Serviceable	196.30 FL	*- FL
19	1		*BOOTLID DAMPER RH	Serviceable	196.30 FL	*- FL
20	1		*BOOTLID INNER COVER	Deformed	198.10 FL	*198.10 FL
21	1		*BOOTLID LOCK	Dented	434.10 FL	*434.10 FL
22	1		*BOOTLID LOCK STRIKER	Bent	83.50 FL	*83.50 FL
23	1		*BOOTLID WEATHERSTRIP (50%)	Distorted / Cut	123.83 FS	*82.55 FS
24	2		*TAIL LAMP	Cracked	960.60 FL	*960.60 FL
25	2		*TAIL LAMP GASKET	Necessary	56.00 FL	*56.00 FL
26	2		*TAIL LAMP CORNER PANEL	Repair	318.20 FL	*- FL
27	1		*REAR EXHAUST	Bent	1,806.40 FL	*1,585.00 FL
28	2		*REAR EXHAUST CHROME	Dented	331.00 FL	*331.00 FL
29	1		*FRONT BUMPER	Buckled	516.30 FL	*516.30 FL
30	1		*FRONT BUMPER TOWING COVER	Serviceable	21.00 FL	*- FL
31	1		*FRONT HEADLAMP LH	Mtg Cracked	1,324.80 FL	*1,324.80 FL
32	1		*FRONT RADIATOR GRILLE	Cracked	468.40 FL	*468.40 FL
33	1		*REAR NUMBER PLATE WITH CASING	Dented	60.00 FS	*45.00 FS
34	1		*SET BOOTLID INNER COVER CLIP	Necessary	30.00 FS	*30.00 FS
35	1		*SET REVERSE SENSORS	Missing	380.00 FS	*380.00 FS
36	1		*FRONT NUMBER PLATE WITH CASING	Dented	60.00 FS	*45.00 FS
37	1		*SET FRONT BUMPER LED LIGHT	Cracked	300.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,338.76	10,562.06
- List Item Discount on L Items 25.00/25.00% (\$)	2,846.23	2,419.88
Total Parts (\$)	9,492.53	8,142.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CUT -OUT DAMAGED PARTS,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	1,600.00	1,100.00
2	TO PUTTY AND SPRAY REPLACED PARTS	New	1,200.00	1,100.00
3	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM	New	80.00	40.00
4	TO APPLY UNDERSEALING	New	60.00	60.00
5	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS TRIM BOARD AND CARPET	New	50.00	50.00
6	TO REMOVE AND RENEW REVERSE SENSORS	New	50.00	50.00
7	TO REMOVE AND RENEW EXHAUST SILENCER BOX	New	180.00	60.00
Gross Labour Cost (\$)			3,220.00	2,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >