

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21011941/AQF3N2**Date:** 09/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070017262-01
Claimant Vehicle No :	PC2165P	Insured Vehicle No :	GBJ2519G
Date of Loss:	22/11/2021	Nature of Claim:	TP
		Claim No:	7372441017SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC2165P		
Make & Model:	MITSUBISHI ROSA, 3.0 D BE641GRMDEB (A)	Engine No:	4M50D72911
Reg. Date:	23/12/2013 (Man. Year: 2012)	Chassis No:	BE63DJF10143
Colour:	White	Odometer:	284825 km
Engine Capacity:	4899 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205R16C	Rear Tyre Size:	205R16C
Front Left Side:	Longway 6 mm	Rear Left Side:	Longway 6 mm
Front Right Side:	Longway 6 mm	Rear Right Side:	Longway 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,323.00	17,272.25	22,050.75	56.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,900.00	5,400.00	4,500.00	45.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	49,223.00	22,672.25	26,550.75	53.94
Approved Total (Overridden) (S\$)		17,000.00		
Nett Amount (S\$)	49,223.00	17,000.00	32,223.00	65.46

INSPECTION

Date of Assignment:	24/11/2021	
Date Inspected:	24/11/2021	Inspected At: JEC AUTO SERVICE PTE LTD (HQ) 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY Singapore 417883
Estimated Period of Repair:	18.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP	Not Necessary	136.00 F	*- FL
2	1		*REAR BUMPER	Distorted	1,652.00 F	*1,652.00 FL
3	2		*REAR BUMPER SIDE HOLDER	Necessary	220.00 F	*220.00 FL
4	2		*REAR BUMPER LAMP	Cracked	308.00 F	*308.00 FL
5	1		*REAR END PANEL	Distorted	899.00 F	*899.00 FL
6	1		*REAR END PANEL INNER FRAME	Distorted	980.00 F	*980.00 FL
7	1		*TAILLAMP	N/s Cracked	580.00 F	*290.00 FL
8	1		*TAILLAMP PANEL LH	Distorted	985.00 F	*985.00 FL
9	1		*REAR LH DOOR	Distorted	3,565.00 F	*3,565.00 FL
10	1		*REAR LH DOOR LOCK	Jammed	345.00 F	*345.00 FL
11	1		*REAR LH DOOR WEATHERSTRIPE	Necessary	256.00 F	*256.00 FL
12	2		*REAR LH DOOR HINGE	Bent	204.00 F	*204.00 FL
13	1		*REAR LH DOOR OUTER HANDLE	Damaged	195.00 F	*195.00 FL
14	1		*REAR LH DOOR INNER TRIM BOARD	Torn	205.00 F	*205.00 FL
15	1		*REAR LH DOOR GLASS MOULDING	Necessary	284.00 F	*284.00 FL
16	1		*REAR RH DOOR	Distorted	1,958.00 F	*1,958.00 FL
17	1		*REAR RH DOOR LOCK	Jammed	325.00 F	*325.00 FL
18	2		*REAR RH DOOR HINGE	Necessary	204.00 F	*204.00 FL
19	1		*REAR RH DOOR WEATHERSTRIPE	Necessary	198.00 F	*198.00 FL
20	1		*REAR RH DOOR INNER TRIM BOARD	Torn	169.00 F	*169.00 FL
21	1		*REAR RH DOOR GLASS MOULDING	Necessary	284.00 F	*284.00 FL
22	1		*TAILLAMP PANEL GLASS LH	Cut	385.00 F	*385.00 FL
23	1		*TAILLAMP PANEL GLASS MOULDING LH	Necessary	145.00 F	*145.00 FL
24	1		*REAR LH SIDE PANEL	Buckled	3,672.00 F	*3,672.00 FL
25	1		*REAR LH SIDE PANEL REFLECTOR	Not Necessary	35.00 F	*- FL
26	1		*REAR LH SIDE PANEL GLASS MOULDING	Necessary	480.00 F	*200.00 FL
27	1		*REAR LH SIDE PANEL INNER TRIM	Torn	295.00 F	*295.00 FL
28	1		*REAR LH SIDE PANEL INNER FRAME	Repair	3,492.00 F	*- FL
29	1		*FLOOR PANEL	Repair	6,800.00 F	*- FL
30	1		*FLOOR PANEL CROSS MEMBER	Repair	1,395.00 F	*- FL
31	1		*REAR CHASSIS CROSS MEMBER	Repair	1,247.00 F	*- FL
32	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
33	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
34	1		*REAR LH DOOR INNER TRIM BOARD CLIPS	Necessary	20.00 FS	*20.00 FS
35	1		*COMPANY NAME STICKER	Necessary	100.00 FS	*80.00 FS
36	1		*60KM/H STICKER	Necessary	15.00 FS	*15.00 FS
37	1		*REAR LH DOOR GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
38	1		*REAR RH DOOR INNER TRIM BOARD CLIPS	Necessary	20.00 FS	*20.00 FS
39	1		*REAR RH DOOR GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
40	1		*REAR RH DOOR COMPANY INFO STICKER	Necessary	200.00 FS	*200.00 FS
41	1		*TAILLAMP PANEL GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
42	1		*REAR CAMERA	Damaged	480.00 FS	*380.00 FS
43	1		*REVERSE SENSOR	Damaged	200.00 FS	*200.00 FS
44	1		*REAR LH SIDE PANEL GLASS SEALANT	Necessary	300.00 FS	*100.00 FS
45	1		*FLOOR PANEL WOODEN BOARD	Cracked	1,800.00 FS	*1,000.00 FS
46	1		*FLOOR PANEL MAT	Torn	2,500.00 FS	*1,000.00 FS
47	1		*REAR UNDER RIDER	Not Necessary	1,000.00 FS	*- FS
48	1		*REAR LH SEAT CUSHION	Torn	500.00 FS	*300.00 FS
49	1		*EMERGENCY DOOR STICKER	Necessary	30.00 FS	*30.00 FS
50	1		*PULL TO OPEN STICKER	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	39,323.00	21,828.00
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	4,555.75
Total Parts (\$\$)	39,323.00	17,272.25

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	4,000.00	2,000.00
2	SPRAY PAINTING	New	2,800.00	1,600.00
3	WIRING	New	100.00	30.00
4	TO SPRAY TUFF COAT	New	300.00	250.00
5	TO REMOVE UPHOLSTERY AND REAR SEATS	New	500.00	380.00
6	TO REMOVE REVERSE SENSOR	New	100.00	50.00
7	TO REMOVE REAR CAMERA	New	100.00	50.00
8	TO TRANSFER REAR DOOR FITTINGS	New	300.00	200.00
9	TO REMOVE REAR DOOR GLASSES	New	300.00	160.00
10	TO REMOVE TAILLAMP PANEL GLASS	New	150.00	80.00
11	TO REMOVE SIDE PANEL GLASSES	New	450.00	200.00
12	TO REPAIR AND STRAIGHTEN CHASSIS MEMBERS	New	800.00	400.00
Gross Labour Cost (\$)			9,900.00	5,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >