

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011942/RS3Q2**Date:** 09/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800020297
Claimant Vehicle No :	SHA5727D	Insured Vehicle No :	SLK8656E
Date of Loss:	23/11/2021	Nature of Claim:	TP
		Claim No:	4267570105SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA5727D		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU674234
Reg. Date:	24/11/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMHU096426
Colour:	Blue	Odometer:	814108 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,706.52	1,901.40	1,805.12	48.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	1,300.00	320.00	19.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,326.52	3,201.40	2,125.12	39.90
Approved Total (Overridden) (S\$)		2,550.00		
(S\$)	5,326.52	2,550.00	2,776.52	52.13
+ GST 7.00/7.00% (S\$)	372.86	178.50	194.36	52.13
Nett Amount (S\$)	5,699.38	2,728.50	2,970.88	52.13
+ Car Rental (2.5 x S\$114.95/day) (S\$)		287.38		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,023.37		

INSPECTION

Date of Assignment:	24/11/2021	
Date Inspected:	24/11/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** Jaslin Kok Chin Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL -FENDER LH	Deformed	663.00 FL	*663.00 FL
2	1		*PANEL ASSY -FR DR LH	Serviceable	2,256.40 FL	*- FL
3	1		*WHEEL ASSY CAP	Scratched	217.20 FL	*217.20 FL
4	1		*MIRROR ASSY -O/S REAR VIEW	Scratched	670.00 FL	*670.00 FL
5	1		*MOULDING ASSY -SIDE SILL L	Deformed	732.80 FL	*732.80 FL
6	1		*FRT DOOR LOGO SONATA CTRL	Necessary	75.00 FS	*75.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,614.40	2,358.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	907.88	456.60
Total Parts (\$\$)	3,706.52	1,901.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	560.00
2	SPRAYPAINT CHARGE	New	600.00	500.00
3	CHECK ALL LIGHTING	New	50.00	20.00
4	TUFF COAT ON AFFECTED PARTS	New	50.00	20.00
5	TRANSFER DOOR PART	New	120.00	0.00
6	RENEW ADVERTISEMENT STICKER -DOOR	New	100.00	100.00
7	RENEW ADVERTISEMENT STICKER -FENDR	New	100.00	100.00
Gross Labour Cost (\$\$)			1,620.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >