

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21011949/EVF3E2

Date: 28/01/2022

REFERENCE

Insured/Claimant:	PHANG KOEI HIONG	Policy No:	2100115365	
Date of Loss:	23/11/2021	Nature of Claim:	OD	Claim No: 9906349328SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM7570M	Engine No:	4G18JT5226
Make & Model:	MITSUBISHI LANCER, 1.3 (A)	Chassis No:	JMYSNCS3A8U007548
Reg. Date:	15/01/2009 (Man. Year: 2008)	Odometer:	167123 km
Colour:	Silver		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	S\$43,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	MARQUIS 5 mm	Rear Left Side:	MARQUIS 5 mm
Front Right Side:	MARQUIS 5 mm	Rear Right Side:	MARQUIS 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,309.58	2,264.71	1,044.87	31.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,745.00	2,010.00	1,735.00	46.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,054.58	4,274.71	2,779.87	39.41
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	6,454.58	3,674.71	2,779.87	43.07
+ GST 7.00/7.00% (S\$)	451.82	257.23	194.59	43.07
Nett Amount (S\$)	6,906.40	3,931.94	2,974.46	43.07

INSPECTION

Date of Assignment:	24/11/2021	
Date Inspected:	25/11/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
2	1		*HEADLAMP ASSY, LH	Broken	624.00 FL	*624.00 FL
3	1		*HORN	Not Necessary	104.00 FL	*- FL
4	1		*FACE, FR BUMPER	Dented	1,081.00 FL	*1,081.00 FL
5	1		*GARNISH, FR LICENSE PLATE	Crushed	46.00 FL	*46.00 FL
6	1		*GARNISH, FR BUMPER, RH	Not Necessary	44.00 FL	*- FL
7	1		*GRILLE, FR BUMPER	Not Necessary	91.00 FL	*- FL
8	1		*PLATE, FR BUMPER, UPR LH	Not Necessary	55.00 FL	*- FL
9	1		*GRILLE, RADIATOR, LH	Cut	106.00 FL	*106.00 FL
10	1		*HOOD	Dented	960.00 FL	*960.00 FL
11	1		*WEATHERSTRIP, HOOD, FR	Not Necessary	39.00 FL	*- FL
12	1		*WEATHERSTRIP, HOOD	Not Necessary	25.00 FL	*- FL
13	1		*RADIATOR ASSY	Not Necessary	973.00 FL	*- FL
14	1		*GARNISH, FR BUMPER	Cut	44.00 FL	*44.00 FL
15	2		*CLIPS (Supplementary)	Necessary	8.00 FL	*8.00 FL
16	10		*CLIPS (Supplementary)	Necessary	30.00 FL	*30.00 FL
17	1		*BULB HALOGEN 60/55 (Supplementary)	Necessary	9.40 FS	*9.40 FS
18	1		*BULB LAMP (Supplementary)	Necessary	4.00 FL	*4.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,283.40	2,932.40
- List Item Discount on L Items 23.00/23.00% (S\$)	973.82	667.69
Total Parts (S\$)	3,309.58	2,264.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER, BONNET, SUPPORT PANEL & AFFECTED AREA	New	1,800.00	675.00
2	PAINT WORK ON FRT BUMPER, BONNET & SUPPORT PANEL	New	1,050.00	700.00
3	REMOVE & INSTALL RADIATOR, CONDENSOR FOR FACILITATE REPAIR	New	120.00	0.00
4	TO TOP UP AIRCON GAS	New	80.00	0.00
5	TO APPLY SEALANT ON AFFECTED AREA	New	80.00	40.00
6	PERFORM RUST PREVENTION	New	40.00	20.00
7	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
9	TO SUPPLY FRT NUMBER PLATE WITH FRAME	New	50.00	50.00
10	REPAIR ON FRONT SUPPORT PANEL (Supplementary)	New	200.00	200.00
11	RESPRAY ON FRONT SUPPORT PANEL (Supplementary)	New	175.00	175.00
Gross Labour Cost (S\$)			3,745.00	2,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >