

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ECICS Limited  
10 Eunos Road 8, #09-04A Singapore Post Centre  
Singapore 408600

**Our File No:** CS/ICS21011954/T1VF3N2**Date:** 13/12/2021**REFERENCE**

Insured/Claimant:	HUNDANI LIE	Policy No:	MPC21P00110100	
Date of Loss:	19/11/2021	Nature of Claim:	OD	Claim No: DMPC2100408H

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SGH7239H</b>	Engine No:	L13A53000426
Make & Model:	HONDA JAZZ, 1.4 (A)	Chassis No:	JHMGD18506S217807
Reg. Date:	20/06/2006 (Man. Year: 2006)	Odometer:	246998 km
Colour:	Blue		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	S\$35,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

**CONDITION OF TYRES**

Front Tyre Size:	185/55R15	Rear Tyre Size:	185/55R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	884.40	438.90	445.50	50.37
Miscellaneous Items	110.00	45.00	65.00	59.09
Labour	1,430.00	930.00	500.00	34.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,424.40</b>	<b>1,413.90</b>	<b>1,010.50</b>	<b>41.68</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>2,424.40</b>	<b>1,100.00</b>	<b>1,324.40</b>	<b>54.63</b>

**INSPECTION**

Date of Assignment:	24/11/2021	
Date Inspected:	29/11/2021	Inspected At: Verve Motorclinic Pte Ltd (Kaki Bukit) No. 25 Kaki Bukit Road 4, #03-39 Synergy@KB Singapore 417800
Estimated Period of Repair:	4.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2021)
<b>Parts:</b>	144	HONDA JAZZ 1.4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGH7239H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		Bumper air grille center, front	Not Necessary	180.00 F	*- F
2	1		Bumper clip, front	Necessary	24.00 F	*24.00 F
3	1		Bumper, front	Deformed	200.00 F	*200.00 F
4	1		Headlamp RH	Cracked	145.00 F	*145.00 F
5	1		*FRT GRILLE EMBLEM	Not Necessary	25.00 F	*- F
6	1		*FRT BUMPER RETAINER RH/LH	Necessary	30.00 F	*30.00 F
7	1		*FRT BUMPER REINFORCEMENT	Not Necessary	80.00 F	*- F
8	1		*FRT SUPPORT PANEL ASSY	Repair	120.00 F	*- F

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>804.00</b>	<b>399.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	80.40	39.90
<b>Total Parts (\$\$)</b>	<b>884.40</b>	<b>438.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	FRT NO PLATE WITH BRACKET Bent	50.00	45.00
2	1	RADIATOR COOLANT Not Necessary	60.00	0.00
<b>Sub Total (\$\$)</b>			<b>110.00</b>	<b>45.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK FRONT ELECTRICAL SYSTEM AND REPAIR WIRE HARNESS	New	50.00	30.00
2	TO REMOVE AND REINSTALL RADIATOR, A/C CONDENSER AND PIPINGS FOR NECESSARY REPAIRS	New	180.00	0.00
3	TO REPAIR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	600.00	400.00
4	TO SPRAY PAINT ON AFFECTED AREA	New	600.00	500.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,430.00</b>	<b>930.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >