

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21011956/URA3Q2**Date:** 09/02/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MPC0006006_01

Claimant Vehicle No : FY4277P **Insured Vehicle No :** SMV6771Z

Date of Loss: 20/11/2021 Nature of Claim: TP Claim No: MPC2021D0005074

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FY4277P**

Make & Model: HONDA CB400SFHV, 399cc Engine No: NC23E2062774

Reg. Date: 16/09/2004 (Man. Year: 2004) Chassis No: NC391052769

Colour: Red Odometer: 195518 km

Engine Capacity: 399 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70-17 Rear Tyre Size: 150/60-17

Front Left Side: Zeneos 6 mm Rear Left Side: Zeneos 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,524.30	4,085.10	8,439.20	67.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	450.00	1,260.00	73.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,234.30	4,535.10	9,699.20	68.14
Approved Total (Overridden) (S\$)		3,600.00		
Nett Amount (S\$)	14,234.30	3,600.00	10,634.30	74.71
+ Loss of Use (6.0 x S\$20.00/day) (S\$)		120.00		
Nett Liability (S\$)		3,720.00		

INSPECTION

Date of Assignment: 24/11/2021

Date Inspected: 25/11/2021 Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)
1 KAKI BUKIT AVE 6 #02-62
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Jan 2022)	
Parts:	N/A	HONDA CB400SFHV 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FY4277P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Not Necessary	245.00 FL	*- FL
2	2		*FORK INNER TUBES	Not Necessary	1,020.00 FL	*- FL
3	2		*FORK OUTER TUBES	Not Necessary	1,040.00 FL	*- FL
4	1		*FORK UNDER BRACKET	Not Necessary	335.00 FL	*- FL
5	1		*FORK UPPER BRACKET	Not Necessary	235.00 FL	*- FL
6	1		*FRONT SPORT RIM	Not Necessary	1,100.00 FL	*- FL
7	1		*FRONT BRAKE DISCS	Not Necessary	1,120.00 FL	*- FL
8	1		*FRONT RIM BEARING	Not Necessary	68.00 FL	*- FL
9	1		*FRONT RIM SHAFT	Not Necessary	128.00 FL	*- FL
10	1		*HEADLAMP	Dented	520.00 FL	*520.00 FL
11	1		*METER	Cut	1,880.00 FL	*305.00 FL
12	1		*HANDLE BAR	Bent / Cut	185.00 FL	*185.00 FL
13	1		*HANDLE BAR END	O/S Cut	105.00 FL	*30.00 FL
14	1		*SET HAND GRIP	Torn	125.00 FL	*68.00 FL
15	1		*SIDE MIRRORS	O/S Cut / N/S Not Necessary	190.00 FL	*95.00 FL
16	1		*BRAKE PEDAL	Cut	98.00 FL	*98.00 FL
17	1		*FRONT SIGNAL -R/H	Broken	180.00 FL	*105.00 FL
18	1		*FRONT FOOTREST -R/H	Cut	75.00 FL	*75.00 FL
19	1		*FRONT FOOTREST BRACKET -R/H	Not Necessary	245.00 FL	*- FL
20	1		*BRAKE PEDAL	Repeated	158.00 FL	*- FL
21	1		*REAR FOOTREST	Not Necessary	105.00 FL	*- FL
22	1		*REAR SIGNALS (O/S)	Cut	185.00 FL	*105.00 FL
23	1		*REAR TAILBOARD	Cracked	385.00 FL	*385.00 FL
24	1		*RADIATOR	Dented	685.00 FL	*585.00 FL
25	1		*RADIATOR SIDE COVER	Bent	85.00 FL	*48.00 FL
26	1		*CLUTCH COVER	Cut	980.00 FL	*395.00 FL
27	1		*EXHAUST & HEADER ASSY	Dented / Cut	1,900.00 FL	*1,380.00 FL
28	1		*FRONT LOWER COVER	Cut	180.00 FL	*160.00 FL
29	1		*SET NUMBER PLATE	Not Necessary	38.00 FS	*- FS
30	2		*FORK OILS	Not Necessary	50.00 FS	*- FS
31	2		*FORK OIL SEALS	Not Necessary	80.00 FS	*- FS
32	1		*SET STEERING CONE	Not Necessary	155.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,880.00	4,539.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,355.70	453.90
Total Parts (\$\$)	12,524.30	4,085.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE	New	50.00	50.00
2	TO CHECK WIRING AND RESET HEADLAMP FORCUSING	New	80.00	0.00
3	TO SRPAY PAINTING	New	480.00	100.00
4	TO PROVIDE LABOUR	New	600.00	300.00
5	TO REPAIR BODY FRAME	New	500.00	0.00
Gross Labour Cost (\$)			1,710.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >