



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2200430

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 19/01/2022
Reference CC3/CTI21011959/R1ea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHB 1432A
Insured Veh. GBH 6767R
Claim No. SNM21D206809/C02
Policy No. DMCVSNW00080942103
Accident Date 20/11/2021
Inspection Date 24/11/2021

| Description | Total |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (7%) | 28.00 |
| Grand Total | 428.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|--|---|-----------------------|
| CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 | | Ref: CC3/CTI21011959/R1ea3q2 Date: 19/01/2022 Code: CTI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | GBH 6767R | Veh. Inspected | SHB 1432A |
| Policy No. | DMCVSNW00080942103 | Coverage (\$) | 0.00 |
| Claim No. | SNM21D206809/C02 | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 24/11/2021 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | TOYOTA PRIUS TAXI (SMRT) | c.c | 1798 |
| Engine No. | HIDDEN | Year of Reg. | 2015 |
| Chassis No. | JTDKN36U605758448 | Colour | MAROON |
| Odometer | 648733 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | FAIR | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 195/65 R15 | SAILUN | 6 mm |
| L/H Front Tyre | 195/65 R15 | SAILUN | 6 mm |
| R/H Rear Tyre | 195/65 R15 | SAILUN | 6 mm |
| L/H Rear Tyre | 195/65 R15 | SAILUN | 6 mm |
| 4. Description of Damages | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS. | | |
| 5. General Information | | | |
| Accident Date | 20/11/2021 | Inspection Date | 24/11/2021 |
| Survey held at | STRIDES AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 | | |
| 5a. Remarks | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | |
| 5b. Estimate Days of Repair | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 4 Working Days |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1432A

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---------------------------------------|----------------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | NAME PLATE (HYBRID) (DISC 25%) | NECESSARY | 51.90 | 38.92 |
| 1 | BUMPER SUPPORT F/LH (DISC 25%) | CRACKED | 76.40 | 57.30 |
| 10 | BUMPER CLIPS @\$1.61 (DISC 25%) | NECESSARY | 16.10 | 12.08 |
| 1 | BUMPER FRT (DISC 25%) | DEFORMED | 482.00 | 361.50 |
| 1 | MIRROR LAMP LH (DISC 10%) | SCRATCHED | 65.30 | 58.77 |
| 1 | ADVERTISEMENT STICKER (SN) | NECESSARY | 445.32 | 148.44 |
| 1 | MIRROR ASSY ,LH | NOT NECESSARY | 1,224.90 | - |
| 1 | STICKER DECAL SMRT (DOOR) | NOT NECESSARY | 60.00 | - |
| 1 | DOOR FRT/LH | NOT NECESSARY | 894.40 | - |
| 1 | MOULDING BODY ,LH | NOT NECESSARY | 673.60 | - |
| 1 | WHEEL HUB FRT | NOT NECESSARY | 549.70 | - |
| 1 | WHEEL DISC ,FRONT | NOT NECESSARY | 1,484.20 | - |
| 1 | TYRE | NOT NECESSARY | 126.74 | - |
| 1 | SEAL ,FRONT FENDER TO COWL SIDE LH | NOT NECESSARY | 15.20 | - |
| 1 | PROTECTOR ,FRONT FENDER SIDE PANEL LH | NOT NECESSARY | 114.50 | - |
| 1 | FENDER LINER PAD ,FR WHEEL ,LH | NOT NECESSARY | 49.30 | - |
| 1 | FENDER LINER FRT/LH | NOT NECESSARY | 171.70 | - |
| 1 | HEAD LAMP LH | NOT NECESSARY | 945.20 | - |
| 1 | SUPPORT SUB-ASSY | NOT NECESSARY | 1,460.40 | - |
| 1 | WIRE ENGINE ROOM NO.3 | NOT NECESSARY | 242.00 | - |
| 1 | BUMPER FRT ABSORBER LOWER | NOT NECESSARY | 127.70 | - |
| 1 | BUMPER LIP FRT | NOT NECESSARY | 139.60 | - |
| 1 | LENS & BODY ,FR TURN LH | NOT NECESSARY | 511.80 | - |
| 1 | FOG LAMP LH | NOT NECESSARY | 280.10 | - |
| 1 | BUMPER GRILLE SUB-ASSY LOWER | NOT NECESSARY | 311.10 | - |
| 1 | BUMPER SUPPORT F/RH | NOT NECESSARY | 76.40 | - |
| 1 | ARM SUB-ASSY ,FR BUMPER LH | NOT NECESSARY | 250.40 | - |
| 1 | BUMPER REINFORCEMENT FRT | NOT NECESSARY | 498.40 | - |
| 1 | BUMPER ENERGY ABSORBER FRT | NOT NECESSARY | 78.80 | - |
| 1 | COVER ,OUTER MIRROR ,LH | TO REPAIR SEE LABOUR | 107.40 | - |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
| 1 | FENDER FRT/LH | TO REPAIR SEE LABOUR | 723.40 | - |
| | | | 12,253.96 | 677.01 |
| | LABOUR | | | |
| | PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF COVER ,OUTER MIRROR ,LH AND FENDER FRT/LH . | | 1,014.00 | 400.00 |
| | SPRAY PAINT. | | 2,034.00 | 460.00 |
| | TOWING CHARGE. | NOT NECESSARY | 56.00 | - |
| | TO CHECK WIRING AND SYSTEM FUNCTION . | NOT NECESSARY | 80.00 | - |
| | TO APPLY RUST-PROOFING ON AFFECTED AREA. | NOT NECESSARY | 100.00 | - |
| | TO DO WHEEL ALIGNMENT /TYRE BALANCING. | NOT NECESSARY | 120.00 | - |
| | TO TRANSFER DOOR MECHANISM . | NOT NECESSARY | 120.00 | - |
| | TO REMOVE AND REFIT WIRE HARDESS. | | 200.00 | 40.00 |
| | TO REPLACE SUNDRY PARTS. | NOT NECESSARY | 100.00 | - |
| | TO WASH AND VACUUM . | NOT NECESSARY | 60.00 | - |
| | | | 3,884.00 | 900.00 |
| | GRAND TOTAL | | 16,137.96 | 1,577.01 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 1,450.00 |

Report Ref No. CC3/CTI21011959/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 1432A

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R










LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 1432A

RE-INSPECTION

