

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011961/KPA3Q2**Date:** 06/04/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SLV2355E **Insured Vehicle No :** SMH5901X
 Date of Loss: 21/11/2021 Nature of Claim: TP Claim No: 8389900008SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV2355E**
 Make & Model: TOYOTA C-HR, 1.2 (A) Engine No: 8NRU089902
 Reg. Date: 26/12/2017 (Man. Year: 2017) Chassis No: NGX502009412
 Colour: Metallic Brown Odometer: 78374 km
 Engine Capacity: 1196 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
 Front Left Side: Pirelli 9 mm Rear Left Side: Pirelli 9 mm
 Front Right Side: Pirelli 9 mm Rear Right Side: Pirelli 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 2,510.20 | 1,258.35 | 1,251.85 | 49.87 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,440.00 | 865.00 | 575.00 | 39.93 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 3,950.20 | 2,123.35 | 1,826.85 | 46.25 |
| + GST 7.00/7.00% (S\$) | 276.51 | 148.63 | 127.88 | 46.25 |
| Nett Amount (S\$) | 4,226.71 | 2,271.98 | 1,954.73 | 46.25 |
| + Loss of Use (4.0 x S\$60.00/day) (S\$) | | 240.00 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| Nett Liability (S\$) | | 2,513.98 | | |

INSPECTION

Date of Assignment: 24/11/2021
 Date Inspected: 26/11/2021 Inspected At: Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
 Autopoint
 Singapore 568047
 Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|------------------|-------------|------------|
| 1 | 2 | | *REAR WINDSCREEN MOULDING SIDE LH & RH | Serviceable | 91.60 FL | *- FL |
| 2 | 1 | | *REAR WINDSCREEN MOULDING LOWER | Serviceable | 68.20 FL | *- FL |
| 3 | 1 | | *TAILGATE | Repair | 1,020.30 FL | *- FL |
| 4 | 1 | | *TAILGATE EMBLEM | Not Necessary | 66.20 FL | *- FL |
| 5 | 1 | | *TAILGATE CHR LOGO | Not Necessary | 45.60 FL | *- FL |
| 6 | 1 | | *REAR BUMPER | Buckled / Dented | 568.20 FL | *568.20 FL |
| 7 | 2 | | *REAR BUMPER SIDE RETAINER LH & RH | Serviceable | 204.40 FL | *- FL |
| 8 | 10 | | *REAR BUMPER CLIPS | Necessary | 45.00 FL | *45.00 FL |
| 9 | 1 | | *REAR BUMPER LOWER GARNISH | Dented | 411.90 FL | *411.90 FL |
| 10 | 1 | | *REAR BUMPER REFLECTOR COVER RH | Serviceable | 95.80 FL | *- FL |
| 11 | 1 | | *REAR BUMPER TOW COVER | Serviceable | 23.70 FL | *- FL |
| 12 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 332.70 FL | *332.70 FL |
| 13 | 1 | | *SEALANT | Not Necessary | 40.00 FS | *- FS |
| 14 | 2 | | *REAR BUMPER CHROME MOULDING LH & RH | Necessary | 40.00 FS | *40.00 FS |
| 15 | 2 | | *REAR BUMPER REVERSE SENSOR | Shorted | 200.00 FS | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 3,253.60 | 1,597.80 |
| - List Item Discount on L Items 25.00/25.00% (\$) | 743.40 | 339.45 |
| Total Parts (\$) | 2,510.20 | 1,258.35 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|---------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING | New | 40.00 | 15.00 |
| 2 | TO REMOVE & REFIT REAR WINDSCREEN | New | 120.00 | 0.00 |
| 3 | TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS | New | 80.00 | 50.00 |
| 4 | TO DISMANTLE ALL DAMAGED PARTS,TO KNOCK & REPAIR END PANEL ,INNER PANELS AND AFFECTED AREAS TO REFIT LISTED PARTS BACK SAME | New | 600.00 | 400.00 |
| 5 | TO SPRAY TAILGATE ,REAR BUMPER ,END PANEL | New | 600.00 | 400.00 |
| | | | Gross Labour Cost (\$\$) | 1,440.00 |
| | | | | 865.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >