

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21011962/EPA3Q2**Date:** 18/02/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0005826_01
Claimant Vehicle No : SGE555G **Insured Vehicle No :** SMZ3770A
 Date of Loss: 21/11/2021 Nature of Claim: TP Claim No: MFL2021D0005077

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGE555G**
 Make & Model: LAMBORGHINI HURACAN, 5.2 LP610-4 (M) Engine No: DGF001064
 Reg. Date: 23/01/2018 (Man. Year: 2017) Chassis No: ZHWED4ZF3JLA08029
 Colour: Yellow Odometer: 2231 km
 Engine Capacity: 5204 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/30Z R20 Rear Tyre Size: 245/30Z R20
 Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
 Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	43,560.24	27,514.92	16,045.32	36.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,900.00	9,800.00	3,100.00	24.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	56,460.24	37,314.92	19,145.32	33.91
+ GST 7.00/7.00% (S\$)	3,952.22	2,612.04	1,340.18	33.91
Nett Amount (S\$)	60,412.46	39,926.96	20,485.50	33.91
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 24/11/2021
 Date Inspected: 24/11/2021 Inspected At: Eurosports Auto Pte Ltd (HQ)
 24 Leng Kee Road #01-03
 Singapore 159096
 Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Feb 2022)

Parts: M1-COUPE LAMBORGHINI HURACAN 5.2 LP610-4 (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGE555G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*EXTERIOR MIRROR	Repair	4,704.00 F	*- F	
2	1		*MIRROR GLASS (CONVEX)	*Check	265.16 F	*- F	
3	1		*WING	Dented	9,075.00 F	*9,075.00 F	
4	2		*COMPENSATING PIEGE	Necessary	29.68 F	*29.68 F	
5	1		*BRACKET (LEFT)	*Check	16.80 F	*- F	
6	1		*DECORATIVE ADHESIVE STRIPS (INCLUDED STICKER LEFT AND RIGHT)	*Check	2,035.60 F	*- F	
7	1		*DECORATIVE ADHESIVE STRIPS (LEFT)	Necessary	170.24 F	*170.24 F	
8	2		*ADHESIVE (MATT BLACK)	*Check	543.76 F	*- F	
9	2		*ALUMINIUM RIM	Cut	18,240.00 F	*18,240.00 F	
10	1		*BRAKE CALIPER HOUSING	Not Necessary	6,780.00 F	*- F	
11	2		*TYRES	*Check	1,700.00 F	*- F	
					Total Parts (S\$)	43,560.24	27,514.92

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REPAIR AND REPLACED DAMAGED PART	New	6,400.00	4,000.00
2	LABOUR TO SPRAY PAINTING NEW PARTS	New	2,000.00	1,300.00
3	PPF (PAINT PROTECTION FILM)	New	4,500.00	4,500.00
			Gross Labour Cost (\$)	12,900.00
				9,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >