

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/GRB21011963/KVF3Q2**Date:** 25/08/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SJS8768Y **Insured Vehicle No :** SLJ7990B
 Date of Loss: 23/11/2021 Nature of Claim: TP Claim No: MFL2021D0005115

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS8768Y**
 Make & Model: HYUNDAI I30 (FD), 1.6 DOHC (A) Engine No: G4FC9U703717
 Reg. Date: 14/09/2009 (Man. Year: 2009) Chassis No: KMHDC81DMAU055103
 Colour: Metallic Red Odometer: 212876 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Kumho 9 mm Rear Left Side: West Lake 6 mm
 Front Right Side: Kumho 9 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,533.28	5,857.44	5,675.84	49.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,380.00	3,060.00	2,320.00	43.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,913.28	8,917.44	7,995.84	47.28
Approved Total (Overridden) (S\$)		7,150.00		
(S\$)	16,913.28	7,150.00	9,763.28	57.73
+ GST 7.00/7.00% (S\$)	1,183.93	500.50	683.43	57.73
Nett Amount (S\$)	18,097.21	7,650.50	10,446.71	57.73

INSPECTION

Date of Assignment: 25/11/2021
 Date Inspected: 25/11/2021 Inspected At: 160 SIN MING DRIVE #05-09 SIN MING AUTOCITY SINGAPORE 575722
 Estimated Period of Repair: 8.0 days Repairer:Hc Auto Pte Ltd (HQ)

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2022)
Parts:	144	HYUNDAI I30 (FD) 1.6 DOHC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS8768Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Torn	460.40 FL	*460.40 FL
2	1		*REAR BUMPER REINFORCEMENT	Cracked	270.00 FL	*270.00 FL
3	1		*REAR BUMPER LOWER LIP	No such part	185.00 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER	O/S Cracked	34.20 FL	*17.10 FL
5	1		*REAR BUMPER BRACKET	O/S Bent	158.40 FL	*79.20 FL
6	1		*REAR BUMPER SPONGE	Torn	129.30 FL	*129.30 FL
7	2		*REAR BUMPER NO PLATE LAMP	Serviceable	124.20 FL	*- FL
8	1		*REAR BUMPER CENTRE LOWER COVER	No such part	78.00 FL	*- FL
9	1		*REAR BUMPER SIDE LOWER COVER	O/S Missing	28.20 FL	*14.10 FL
10	1		*O/S TAIL LAMP	Broken	533.60 FL	*447.50 FL
11	1		*O/S TAIL LAMP LOWER CLIP	Necessary	4.00 FL	*4.00 FL
12	1		*TAIL GATE	Bent	2,045.70 FL	*1,501.00 FL
13	1		*TAIL GATE INNER LOCK	Repair	166.80 FL	*- FL
14	1		*TAIL GATE HYUNDAI EMBLEM	Necessary	26.10 FL	*26.10 FL
15	1		*TAIL GATE HYUNDAI LOGO	Necessary	31.20 FL	*31.20 FL
16	1		*TAIL GATE I 30 CW EMBLEM	Necessary	42.00 FL	*42.00 FL
17	1		*TAIL GATE INNER TRIM BOARD	Serviceable	232.30 FL	*- FL
18	1		*TAIL GATE LOWER HOLDER	Serviceable	236.30 FL	*- FL
19	2		*TAIL GATE DAMPER	Serviceable	124.80 FL	*- FL
20	1		*O/S REAR FENDER	Bent	1,842.00 FL	*1,243.00 FL
21	1		*O/S REAR FENDER OUTER GARNISH	No such part	128.00 FL	*- FL
22	1		*O/S REAR FENDER AIR DUCT	Missing	32.80 FL	*32.80 FL
23	1		*O/S REAR FENDER OUTER SHIELD	Cracked	35.00 FL	*35.00 FL
24	1		*O/S REAR FENDER INNER GARNISH	Cracked	163.00 FL	*163.00 FL
25	1		*O/S REAR WHEEL HOUSE	Repair	1,095.50 FL	*- FL
26	1		*O/S REAR LOWER ARM	Distorted	239.60 FL	*239.60 FL
27	1		*O/S REAR TRAILING ARM	Bent	225.80 FL	*225.80 FL
28	1		*O/S REAR WHEEL BEARING WITH HUB	Bent	394.50 FL	*394.50 FL
29	1		*O/S REAR SHOCK ABSORBER	Bent	223.00 FL	*223.00 FL
30	1		*REAR END PANEL	Bent	499.30 FL	*489.00 FL
31	1		*REAR END PANEL INNER GARNISH	Mtg Cracked	59.00 FL	*59.00 FL
32	1		*O/S REAR DOOR	Repair	1,837.70 FL	*- FL
33	1		*O/S REAR DOOR INNER LOCK	Repair	246.50 FL	*- FL
34	1		*O/S REAR DOOR RUBBER	Serviceable	124.80 FL	*- FL
35	1		*REAR SPARE TYRE BOARD	Serviceable	316.70 FL	*- FL
36	1		*REAR EXHAUST BOX	Bent	711.20 FL	*711.20 FL
37	1		*REAR EXHAUST BOX GARNISH	Serviceable	113.30 FL	*- FL
38	1		*REAR WEATHERSTRIP	Serviceable	84.40 FL	*- FL
39	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	109.00 FL	*109.00 FL
40	1		*SET REAR BUMPER REVERSE SENSOR	Scratched	350.00 FS	*200.00 FS
41	1		*REAR BUMPER NO PLATE	Serviceable	100.00 FS	*- FS
42	1		*REAR END PANEL SEAL	Necessary	250.00 FS	*30.00 FS
43	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	60.00 FS	*30.00 FS
44	1		*REAR WINDSCREEN GLASS INNER GUM	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **14,211.60** **7,246.80**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 20.00/20.00% (S\$)					2,678.32	1,389.36
Total Parts (S\$)					11,533.28	5,857.44
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES	New	2,200.00	1,200.00
2	TO PUTTY AND SPRAY PAINTING	New	1,800.00	1,200.00
3	RE-SEAL ANTI RUST	New	200.00	90.00
4	TO CHECK ,REPLACE ,REPAIR WIRING	New	120.00	20.00
5	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	160.00	120.00
6	REMOVE AND REFIX CUSHION SEAT ,GARNISH ,CARPET ,ETC	New	180.00	120.00
7	REMOVE AND REFIX EXHAUST BOX	New	120.00	60.00
8	REMOVE AND REFIX REAR UNDERCARRIAGE	New	380.00	140.00
9	TO CHECK WHEEL ALIGNMENT	New	120.00	60.00
10	REMOVE AND REFIX REAR REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			5,380.00	3,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >