

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21011973/EQF3E2**Date:** 03/01/2022**REFERENCE**

Insured/Claimant:	ANG PAU YONG	Policy No:	2100492176-04	
Date of Loss:	05/11/2021	Nature of Claim:	OD	Claim No: 9625354581SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ1837B	Engine No:	G4FGGH658434
Make & Model:	KIA FORTE K3, 1.6 (A)	Chassis No:	KNAFX411MH5668425
Reg. Date:	30/11/2016 (Man. Year: 2016)	Odometer:	81998 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$50,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,486.40	3,299.60	186.80	5.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,300.00	1,040.00	44.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,826.40	4,599.60	1,226.80	21.06
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	5,526.40	4,299.60	1,226.80	22.20
+ GST 7.00/7.00% (S\$)	386.85	300.97	85.88	22.20
Nett Amount (S\$)	5,913.25	4,600.57	1,312.68	22.20

INSPECTION

Date of Assignment:	25/11/2021	
Date Inspected:	26/11/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
2	1		*LAMP ASSY-HEAD, LH	Broken	1,707.00 FL	*1,707.00 FL
3	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
4	1		*COVER-FR BUMPER	Dented	633.00 FL	*633.00 FL
5	1		*MOULDING-FRT BPR LICENSE PLATE	Broken	18.00 FL	*18.00 FL
6	1		*LIP ASSY-FRONT BUMPER	Not Necessary	55.00 FL	*- FL
7	1		*DUCT ASSY-AIR CURTAIN, LH	Not Necessary	6.00 FL	*- FL
8	1		*AIR DUCT-FR BUMPER, LH	Not Necessary	33.00 FL	*- FL
9	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 FL	*84.00 FL
10	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
11	1		*RAIL ASSY-FR BUMPER	Broken	496.00 FL	*496.00 FL
12	1		*BRACKET-FR BUMPER SIDE MTG, LH	Not Necessary	13.00 FL	*- FL
13	1		*GRILLE ASSY-RADIATOR	Cut	328.00 FL	*328.00 FL
14	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
15	1		*GARNISH-RADIATOR GRILLE, UPR (Supplementary)	Broken	54.00 FL	*54.00 FL
16	10		*CLIPS (Supplementary)	Necessary	10.00 FL	*10.00 FL
17	1		*FRT NUMBER PLATE WITH FRAME	Cut	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,338.00	4,107.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	851.60	807.40
Total Parts (\$\$)	3,486.40	3,299.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER, SUPPORT & AFFECTED AREA	New	1,200.00	400.00
2	PAINT WORK ON FRT BUMPER PANEL	New	350.00	350.00
3	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR	New	120.00	0.00
4	TO TOP UP AIRCON GAS	New	80.00	0.00
5	PERFORM RUST PREVENTION	New	40.00	0.00
6	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
8	REPLACE FRONT SUPPORT PANEL (Supplementary)	New	400.00	400.00
Gross Labour Cost (S\$)			2,340.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >