

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21011976/KGA3Q2**Date:** 20/05/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SKU2082J	Insured Vehicle No :	SLL9594M
Date of Loss:	17/11/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0005056

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU2082J	Engine No:	A25A0207447
Make & Model:	TOYOTA CAMRY, 2.5 HYBRID CVT (A)	Chassis No:	AXVH701031457
Reg. Date:	26/12/2019 (Man. Year: 2018)	Odometer:	25662 km
Colour:	Metallic Silver		
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,514.74	2,150.13	4,364.61	67.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	895.00	565.00	38.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,974.74	3,045.13	4,929.61	61.82
+ GST 7.00/7.00% (S\$)	558.23	213.16	345.07	61.82
Nett Amount (S\$)	8,532.97	3,258.29	5,274.68	61.82
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,665.74		

INSPECTION

Date of Assignment:	25/11/2021	Ah Lim Motor Company (AMK)
Date Inspected:	26/11/2021 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
Estimated Period of Repair:	3.0 days	Autopoint
		Singapore 568047

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 06 May 2022)**Parts:** 143 TOYOTA CAMRY 2.5 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SKU2082J)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	1,143.70 FL	*1,143.70 FL
2	1		*REAR BOOT EMBLEM	Necessary	47.90 FL	*47.90 FL
3	1		*REAR BOOT CAMRY LOGO	Not Necessary	70.20 FL	*- FL
4	1		*REAR BOOT HYBRID SYNERGY DRIVE LOGO	Necessary	65.80 FL	*65.80 FL
5	2		*REAR BOOT LAMP LH & RH	Serviceable	1,201.90 FL	*- FL
6	2		*REAR BOOT NO PLATE LAMP LH & RH	Serviceable	323.40 FL	*- FL
7	1		*REAR BOOT NO PLATE GARNISH	Serviceable	211.67 FL	*- FL
8	1		*REAR BOOT LOCK	Repair	498.10 FL	*- FL
9	1		*REAR BOOT LOCK CATCH	Repair	28.90 FL	*- FL
10	1		*REAR BOOT RUBBER	Serviceable	227.80 FL	*- FL
11	2		*TAILLAMP LH & RH	Serviceable	1,561.90 FL	*- FL
12	2		*TAILAMP LOWER BEAM LH & RH	Serviceable	245.20 FL	*- FL
13	2		*TAILAMP COVER LH & RH	Serviceable	135.60 FL	*- FL
14	1		*REAR BUMPER	Buckled	721.90 FL	*721.90 FL
15	1		*REAR BUMPER LOWER GARNISH	Dented	433.70 FL	*433.70 FL
16	2		*REAR BUMPER LOWER GARNISH REFLECTOR LH & RH	Serviceable	163.80 FL	*- FL
17	2		*REAR BUMPER SIDE RETAINER LH & RH	Serviceable	262.14 FL	*- FL
18	12		*REAR BUMPER CLIPS	Necessary	54.00 FL	*54.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Damaged	399.84 FL	*399.84 FL
20	1		*REAR END PANEL GARNISH	Serviceable	399.84 FL	*- FL
21	1		*EXHAUST PIPE TAIL	Serviceable	175.70 FL	*- FL
22	1		*REAR CAMERA (NPA)	Serviceable	0.00 FS	*- FS
23	1		*NUMBER PLATE	Serviceable	35.00 FS	*- FS
24	1		*SET REVERSE SENSOR	Serviceable	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,607.99	2,866.84
- List Item Discount on L Items 25.00/25.00% (S\$)	2,093.25	716.71
Total Parts (S\$)	6,514.74	2,150.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	15.00
2	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	50.00
3	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
4	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD ,TO KNOCK & REPAIR REAR END PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	600.00	400.00
5	TO SPRAY REAR BOOT ,REAR BUMPER ,REAR END PANEL	New	700.00	400.00
			Gross Labour Cost (\$\$)	1,460.00
				895.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >