



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC21011982/Bqf3e2	
			Date: 10/02/2022	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBG 9884X	Veh. Inspected	GBA 1411L
	Policy No.		Coverage (\$)	0.00
	Claim No.	20/21/21/VC05/025181	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	25/11/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE MT	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	JTFHT02P300002823	Colour	SILVER
	Odometer	376412 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	POOR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	YOKOHAMA	4 mm
	L/H Front Tyre	195 R15C	YOKOHAMA	4 mm
	R/H Rear Tyre	195 R15C	CST	4 mm
	L/H Rear Tyre	195 R15C	CST	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/11/2021	Inspection Date	25/11/2021
	Survey held at	GUAN AUTO SERVICE BLK12 #01-59 SIN MING INDUSTRIAL ESTATE SECTOR B SINGAPORE 575656		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	