

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21011985/VEA3Q2**Date:** 19/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100397297
Claimant Vehicle No :	SHD1052C	Insured Vehicle No :	EH1218G
Date of Loss:	15/11/2021	Nature of Claim:	TP
		Claim No:	6573606580SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD1052C	Engine No:	D4FDFH314451
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5658868
Reg. Date:	21/01/2016 (Man. Year: 2015)	Odometer:	699404 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	206/60 R16	Rear Tyre Size:	206/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	443.60	48.00	395.60	89.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	360.00	140.00	28.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	943.60	408.00	535.60	56.76
+ GST 7.00/7.00% (S\$)	66.05	28.56	37.49	56.76
Nett Amount (S\$)	1,009.65	436.56	573.09	56.76
+ Loss of Use (2.0 x S\$40.00/day) (S\$)		80.00		
+ Car Rental (2.0 x S\$67.41/day) (S\$)		134.82		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		653.38		
Global Sum Settlement (S\$)		650.00		

INSPECTION

Date of Assignment:	23/12/2021		Premier Automotive Services Pte Ltd (HQ)
Date Inspected:	23/12/2021	Inspected At:	23 Changi South Ave 2, #01-02
			Singapore 486443
Estimated Period of Repair:	2.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S FENDER LH	Repair	384.00 FL	*- FL
2	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	48.00 FS	*48.00 FS
3	1		*SUNDRY	Serviceable	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	482.00 48.00
					- List Item Discount on L Items 10.00/10.00% (\$)	38.40 0.00
					Total Parts (\$)	443.60 48.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE SAME	New	250.00	180.00
2	TO PUTTY AND SRPAY PAINTING ON FRONT BUMPER ,FRONT N/S FENDER	New	250.00	180.00
Gross Labour Cost (\$\$)			500.00	360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >